

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

**Estimate**

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-297  
DATE : 6-Jun-2022  
POLICY NO. : DA MT/00806050  
VEHICLE REG. NO. : SLR591Z  
VEHICLE MAKE : SUBARU XV 1.6I-S AWD CVT

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

**FOR SURVEYOR**

--

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<b><u>SPARE PARTS</u></b>			
1	Rear Bumper	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
4	Rear Bumper Retainer LH	1	\$ 50.00	\$ 50.00
5	Rear Bumper Corner Bracket RH - 57707AC	1	\$ 60.00	\$ 60.00
6	Rear Bumper Corner Bracket LH - 57707AD	1	\$ 60.00	\$ 60.00
7	Rear Bumper Lower Bracket - 57707N	1	\$ 60.00	\$ 60.00
8	Rear Bumper Reflector RH	1	\$ 50.00	\$ 50.00
9	Rear Bumper Reflector LH	1	\$ 50.00	\$ 50.00
10	Rear Bumper Tow Eye Cover	1	\$ 60.00	\$ 60.00
11	Rear Bumper Protector Guard	1	\$ 580.00	\$ 580.00
12	Rear Bumper Foglamp	1	\$ 220.00	\$ 220.00
13	Rear Reinforcement	1	\$ 420.00	\$ 420.00
14	Rear Tail Lamp RH	1	\$ 550.00	\$ 550.00
15	Rear Tail Lamp LH	1	\$ 550.00	\$ 550.00
16	Rear Tailgate	1	\$ 900.00	\$ 900.00
17	Rear Tailgate Lock	1	\$ 250.00	\$ 250.00
18	Rear Tailgate Rubber Seal	1	\$ 160.00	\$ 160.00
19	Rear SUBARU Emblem	1	\$ 90.00	\$ 90.00
20	Rear AWD Emblem	1	\$ 90.00	\$ 90.00
21	Rear XV Emblem	1	\$ 60.00	\$ 60.00
22	Rear End Panel	1	\$ 500.00	\$ 500.00
23	Rear End Panel Garnish	1	\$ 180.00	\$ 180.00
24	Rear Exhaust	1	\$ 780.00	\$ 780.00
25	Rear Exhaust Rubber Mount	2	\$ 60.00	\$ 120.00
<b>Total Spare Parts</b>				<b>\$ 6,620.00</b>
	<b><u>SPECIAL NETT</u></b>			
26	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
27	Rear License Plate	1	\$ 40.00	\$ 40.00
28	Reverse Sensor	1	\$ 200.00	\$ 200.00
<b>Total Special Nett</b>				<b>\$ 280.00</b>
	<b><u>LABOUR</u></b>			
29	Spray Paint Rear Bumper, Tailgate and Inner Panel	1	\$ 1,000.00	\$ 1,000.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2206-297

DATE : 6-Jun-2022

POLICY NO. : DA MT/00806050

VEHICLE REG. NO. : SLR591Z

VEHICLE MAKE : SUBARU XV 1.6I-S AWD CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
30	Replace & Refit Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
31	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
32	Remove and Replace Rear Windscreen	1	\$ 120.00	\$ 120.00
33	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
34	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
35	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
36	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

**Estimate prepared by: Oscar Pong**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,490.00
Amount Before Excess	\$ 9,390.00
Add GST @ 7%	657.30
Total Amount Payable	\$ 10,047.30