

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	9607198-R	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI22005694/Uvy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 30/06/2022	
			Co	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBQ 5537Y	Veh. Inspected	SKP 2708P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C20015707 /JT	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	15/06/2022	
2. Vehicle Particulars & Condition					
	Make & Model	AUDI A3 SB (A)	c.c	1395	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WAUZZZ8V2EA156508	Colour	WHITE	
	Odometer	98045 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/06/2022	Inspection Date	20/06/2022	
	Survey held at	PRECISE AUTO SERVICE			
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	DJIN ACCORDANC	Estimate Days of Repair			
	Estimate Days of Nepall				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: