

(08/11/13) wef

ASS. REC. BY: Pone

REF:

369K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SHB 5364Lat Workshop m/s STRIDS (SMRT)of 60 power windows (add PK 44)Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 20K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 5364LYr Regn: 2016 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS TAXI (SMRT) c.c 1798Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN 36400 576 7470Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILUN

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 07/06/22D.O.I. 09/06/22

Survey held at

STRIDSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 8K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



Case Details

Case Reference Number :

TAX/06/22/2024

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5364L

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18494-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 07/06/2022 09:05 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Rem
Standard	Main			BUMPER REAR	1	458.60	343.95	25.00	343.95	Replace	1	343.9	Replace	ca ✓
Standard	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	re ✓
Standard	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.2	Replace	bt ✓
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.7	Replace	bt ✓
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.7	Replace	bt ✓
Standard	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	1	141.6	Replace	ca ✓
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	rw ✓
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	?
Standard	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	?
Standard	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Check	?
Standard	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Check	?
Standard	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	sea ✓
Standard	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	sea ✓
Standard	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	sea ✓

Total Spare Part Cost 29,225.55

Surveyor Total 6,028.35

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Rem
Standard	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.8	Replace	✓ MIS ✓
Standard	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	✓ ?
Standard	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.93	Replace	0	0	Check	✓ ?
Standard	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.5	Replace	✓ BT ✓
Standard	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	✓ ?
Standard	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	✓ ?
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ ne ✓
Standard	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check	✓ ?
Standard	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	1	509.7	Replace	✓ der
Standard	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give	✓ Xn
Standard	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.58	Replace	0	0	Not Give	✓ Xn
Standard	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Not Give	✓ Xn
Standard	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Not Give	✓ Xn
Standard	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Not Give	✓ Xn
Standard	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Not Give	✓ Xn
Standard	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Not Give	✓ Xn
Standard	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	✓ Xn
Standard	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair	✓ R
Standard	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	✓ Xn
Standard	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	✓ Xn
Standard	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Not Give	✓ Xn
Standard	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.58	Replace	0	0	Not Give	✓ Xn
Standard	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.58	Replace	0	0	Not Give	✓ Xn
Standard	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Not Give	✓ Xn

Total Spare Part Cost 29,225.55

Surveyor Total 6,028.35

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 22,985.59

Final Sur Total 4,822.68

SMRT Recommendation

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Rem
Standard	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Not Give	X11
Standard	Main			MEMBER SUB-ASSY, REAR FLOOR CROSS NO.1	1	436.40	436.40	25.00	327.30	Replace	0	0	Not Give	X11
Standard	Main			MEMBER SUB-ASSY, REAR FLOOR CROSS NO.2	1	655.70	655.70	25.00	491.78	Replace	0	0	Not Give	X11
Standard	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Not Give	X11
Standard	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Not Give	X11
Standard	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Not Give	X11
Standard	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Not Give	X11
Standard	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	X11
Standard	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give	X11
Standard	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	X11
Standard	Main			BATTERY ASSY, HV	1	5,544.40	5,544.40	10.00	4,989.96	Replace	0	0	Not Give	X11
Standard	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Not Give	X11
Standard	Main			TERMINAL, JUNCTION	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	X11
Standard	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Not Give	X11
Standard	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Not Give	X11
Standard	Main			WIRE, FRAME	1	1,680.90	1,680.90	10.00	1,512.81	Replace	0	0	Not Give	X11
Standard	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.93	Replace	1	755.9	Replace	new
Standard	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	new
Standard	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	22.05	25.00	22.05	Replace	1	22.05	Replace	new
Standard	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	0	0	Not Give	X11
Standard	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Check	?
Standard	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	0	0	Check	?
Standard	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	0	0	Not Give	X11

Total Spare Part Cost 29,225.55

Lump Sum Discount (%) 20.00

Final Spare Part Cost 22,985.59

Surveyor Total 6,028.35

Lump Sum Dis (%) 20.00

Final Sur Total 4,822.68

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Rem
Standard	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	28.90	57.80	25.00	43.35	Replace	0	0	Not Give	Xm
Standard	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	0	0	Not Give	Xm
Standard	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Not Give	Xm
Standard	Main			SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	nm
Standard	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Not Give	Xm
Standard	Main			MOTOR ASSY, RR WIPER	1	734.60	734.60	10.00	661.14	Replace	0	0	Not Give	Xm
Standard	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Not Give	Xm
Standard	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.0	Replace	bf
Standard	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	1	11.77	Replace	sol
Standard	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.68	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.0	Replace	nm
Standard	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.23	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Not Give	Xm
Standard	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	1	185.1	Replace	bf
Standard	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Check	?
Standard	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	Xm
Standard	Main			LICENSE PLATE LAMP	2	35.70	71.40	25.00	53.55	Replace	0	0	Not Give	Xm

Total Spare Part Cost 29,225.55

Surveyor Total 6,028.35

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 22,985.59

Final Sur Total 4,822.68

SMRT Recommendation										Surveyor Approval					
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Rem	
Standard	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Not Give	Xm	
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	1	38.92	Replace	neo	
Standard	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Check	?	
Standard	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.93	Replace	0	0	Check	?	
Standard	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	bfr	
Standard	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	cut	
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Check	?	
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Check	?	
Standard	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	Xm	
Standard	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	Xm	
Standard	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	Xm	
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xm	
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xm	
Standard	Main			FENDER LINE RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	Xm	
Standard	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.03	Replace	0	0	Check	?	
Standard	Main			TAIL LAMP RH	1	557.80	557.80	25.00	418.35	Replace	1	418.3	Replace	con	
Standard	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.1	Replace	buc	
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	neo	
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	neo	
Standard	Main			STICKER PETROL ONLY	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	Xm	
Standard	Main			FENDER LINER R/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	Xm	
Standard	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.03	Replace	0	0	Check	?	
Standard	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.5	Replace	con	
Total Spare Part Cost									29,225.55	Surveyor Total		6,028.35			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00			
Final Spare Part Cost									22,985.59	Final Sur Total		4,822.68			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	1,000.00	
Total:			1,690.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY FLOOR CORNER PANEL LH	180.00	0.00 XM	
3	Main	TO RESPRAY FLOOR CORNER PANEL RH	180.00	0.00 XM	
4	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 XM	
5	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 XM	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00	
7	Main	TO RESPRAY REAR SPOILER	180.00	0.00 XM	
8	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 XM	
9	Main	TO RESPRAY TAIL GATE	378.00	200.00	
10	Main	TO RESPRAY REAR FENDER RH	378.00	0.00 XM	
11	Main	TO RESPRAY REAR FENDER LH	378.00	200.00	
12	Main	TO RESPRAY REAR PANEL	180.00	100.00 }	
Total:			2,952.00	800.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0.00 7,	provide receipt
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40.00	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	80.00	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00	
Total:			1,366.00	340.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00	
6	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00	
7	Main	TO REMOVE AND REFIT BATTERY ASSY HV	250.00	0.00 <i>Xm</i>	
8	Main	TO WASH AND VACUUM	60.00	0.00 <i>Xm</i>	
9	Main	TO REPLACE SUNDRY PARTS	200.00	0.00 <i>Xm</i>	
Total:			1,366.00	340.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	22,985.59	4,822.68
Total Labour Cost	1,690.00	1,000.00
Total Spray Painting	2,952.00	800.00
Other	1,366.00	340.00
Overall Total	28,993.59	6,962.68
Lump Sum Repair Option	☐	☒
Lump Sum Total	29,000.00	6,950.00
Surveyor Approved Amount		6,950.00
No of Repair Days*	10	8
Remarks	-	resurvey after repair photo , need NBV.
Surveyor Name		Rasul
Signature		

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/06/2022 08:55 (SGT)
Date of Accident	07/06/2022 17:05 (SGT)
Exact Location of Accident	Orchard Rd, Singapore
Additional Location Information	ORCHARD ROAD TOWARDS BRAS BASHA ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5364L
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

DRIVER

Name of Driver	TEO MENG WEE
NRIC No	SXXXX467A

Date Of Birth	02/11/1970
Occupation	Outdoor
Date Of Driving Pass	22/01/1991
Driving experience	31 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG ORCHARD ROAD TOWARDS BRAS BASAH ROAD. A VEHICLE IN FRONT OF MY TAXI CAME TO A HALT AND I STOPPED TOO. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLA4050G HAD COLLIDED WITH THE REAR OF MY TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA4050G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM YU XIAN
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

 Sketch Plan

08/06/22
 0855 hrs.
 Driver's Signature (If driver is not the policyholder) / Date & Time

86.2022
 Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5364L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6579907
Chassis No.:	JTDKN36U005767470
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	04 Mar 2016
First Registration Date:	04 Mar 2016
Transfer Count: -	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Mar 2024
PARF Rebate Amount:	\$3,250.00
COE Expiry Date:	03 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$8,524.00
Total Rebate Amount:	\$11,774.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jun 2022

OK