



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO22005696/Kvy3

50 RAFFLES PLACE #03-03

Date: 15/06/2022

SINGAPORE LAND TOWERSINGAPORE 048623

Code: SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GBE 5390R
Policy No.	Coverage (\$)	0.00
Claim No. CMTD2202073/AGC	Excess (\$)	0.00
Assign From GRACE TEO	Assign Date	15/06/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/06/2022	Inspection Date	15/06/2022
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.