



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22005699/Gvy3q2 Date: 16/08/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 9250X	Veh. Inspected	SNA 6460U
	Policy No.	D-22099102MFCV/12	Coverage (\$)	0.00
	Claim No.	D22001746MFCV	Excess (\$)	0.00
	Assign From	AINI	Assign Date	15/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC 1.8L	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JHMF16308S215339	Colour	SILVER
	Odometer	136703 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55Z R16	MICHELIN	6 mm
	L/H Front Tyre	205/55Z R16	MICHELIN	6 mm
	R/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
	L/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/06/2022	Inspection Date	13/07/2022
	Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	