

ABWIN SERVICE PTE LTD
17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G



ESTIMATED COST: HQQ000640

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

SNA6460U
KHAIRUL IKHSAN BIN YUSOFF
BLK 632C
TAMPINES AVENUE 12
#04-97
SINGAPORE,
SINGAPORE 523623
CONTACT NO : 96585443

DATE : 22-JUN-2022
MAKE : HONDA
MODEL : CIVIC 1.8L A
CHASSIS NO : JHMFD16308S215339
ENGINE NO : R18A13033739
SERVICE ADVISOR : HAZEL
PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	FRONT BUMPER X Repair	631.30	
1	FRONT BUMPER BRACKET RH X NN	256.60	
1	FRONT BUMPER SIDE RETAINER RH ✓ CUT	21.50	✓
1	HEADLAMP RH ✓ BR	912.10	✓
1	HEADLAMP BRACKET RH ✓ BT	34.20	✓
1	FRONT BUMPER FOG LAMP RH - CRA	250.20	✓
1	FRONT FENDER RH X Repair	450.80	
1	FRONT FENDER INNERSHIELD RH X } NN	111.20	
1	SUPPORT PANEL X	549.80	
Sub Total		3,217.70	1218 0.00

-20%: 974.4

SPECIAL NETT			
10	FRONT BUMPER CLIPS X NN	50.00	
10	HEADLAMP CLIPS X	50.00	
10	FRONT FENDER INNERSHIELD CLIPS X } NN	50.00	
Sub Total		150.00	0.00

LABOUR			
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	200
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	400
1	TO APPLY TUFF COAT ON AFFECTED AREAS	150.00	X NN
Sub Total		1,750.00	1574.4 0.00

-20%: 1250

3 Days.
Lump sum repair
After repair photos.
Guo Qiang - 82880282
13/7/22.
Guo Qiang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display items for appraisal during resurvey
- Parts prices are on a "no prejudice" basis
- Third party, not a "no prejudice" basis
- No fee for resurvey
- Supplies and materials surveyed and is subject to the Insurance Company

Acknowledged by _____
Signed by _____
Dated _____