

ABWIN SERVICE PTE LTD
17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G



ESTIMATED COST: HQQ000640

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

SNA6460U
KHAIRUL IKHSAN BIN YUSOFF
BLK 632C
TAMPINES AVENUE 12
#04-97
SINGAPORE,
SINGAPORE 523623
CONTACT NO : 96585443

DATE : 22-JUN-2022
MAKE : HONDA
MODEL : CIVIC 1.8L A
CHASSIS NO : JHMFD16308S215339
ENGINE NO : R18A13033739
SERVICE ADVISOR : HAZEL
PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT BUMPER <i>X Repair</i>	631.30	
1	FRONT BUMPER BRACKET RH <i>X NN</i>	256.60	
1	FRONT BUMPER SIDE RETAINER RH <i>?</i>	21.50	
1	HEADLAMP RH <i>?</i>	912.10	
1	HEADLAMP BRACKET RH <i>?</i>	34.20	
1	FRONT BUMPER FOG LAMP RH <i>- CRA</i>	250.20	
1	FRONT FENDER RH <i>X Repair</i>	450.80	
1	FRONT FENDER INNERSHIELD RH <i>X NN</i>	111.20	
1	SUPPORT PANEL <i>X</i>	549.80	
Sub Total		3,217.70	0.00

SPECIAL NETT

10	FRONT BUMPER CLIPS <i>?</i>	50.00	
10	HEADLAMP CLIPS <i>X</i>	50.00	
10	FRONT FENDER INNERSHIELD CLIPS <i>X NN</i>	50.00	
Sub Total		150.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	<i>200</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	<i>400</i>
1	TO APPLY TUFF COAT ON AFFECTED AREAS	150.00	<i>X NN</i>
Sub Total		1,750.00	0.00

3 Days.
Lump sum repair
After repair photos.
Guo Qiang - 82880282
13/7/22.
Guo Qiang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display items for appraisal during resurvey
• Parts prices are on a "no prejudice" basis
• Third party, no prejudice basis
• No prejudice basis for survey and
is subject to the insurance Company
Acknowledge
Signature
Date