



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10 June 2022

MS First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore (068877)

Dear Sirs,

RE: Cost of repair to Yamaha T155 - FBT2007P

1pc of Front Fork Comp ? / BT
1pc of Body Set / CUT
1pc of Front Mudguard / CUT
1pc of Handle Bar / BT
1pc of Brake Lever / BT
1pc of Handle Balancer / CUT
1pc of Handle Pedal (Rear pedal) / BT
1pc of Exhaust Pipe / BT
1pc of Mirror / MIS
1pc of Rear Box / MIS
1pc of Rear Box Bracket / BT
1pc of Front Footrest Bracket / BT
1pc of Front Footrest / CUT
1pc of Front Signal / CUT
1pc of Centre Box / CUT
1pc of Brake Disk / BT
1pc of Clutch Lever / CUT
1pc of Gasket / ACC

~~LH magnetic cover \$185 / ACC~~
~~Double Stand 95.00 / BT~~
~~RH clutch cover \$190 / ENT~~
~~EXHAUST COVER (front & rear) \$65 / ENT~~

Less 10%

Nett

Transport

Jack Body & Alignment

LTA Fees

Engine Oil


Labour

580.00	500/-
850.00	400/-
75.00	/
85.00	/
25.00	/
20.00	/
55.00	/
480.00	400/-
50.00	/
235.00	200/-
160.00	130/-
120.00	/
65.00	/
95.00	/
145.00	100/-
165.00	140/-
190.00	35/-
25.00	/
3,420.00	2520
342.00	-10%
3,078.00	2268
40.00	/
250.00	? X
7.45	X
20.00	/ NEC
300.00	200
<u>\$3,695.45</u>	260

Supp-481-50
3009.50

L/S-2407.60
=2400

Yours Faithfully,
Southern Motor





南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

10-June-2022

MS First Capital Insurance Limited

36 Robinson Road #16-01

City House

Singapore (068877)

Dear Sirs,

RE: Additional Cost of repair to Yamaha T155 – FBT2007P

1pc of Magneto Cover LH	✓ BR	S\$	185.00
1pc of Double Stand	✓ BT		95.00
1pc of Clutch Cover RH	✓ CUT		190.00
1pc of Front & Rear Exhaust Cover	✓ CUT		65.00
			535.00
	Less 10%		53.50
	Nett		481.50

Yours Faithfully,
Southern Motor

Steve (LKK)
15/06/22

