



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

10-June-2022

MS First Capital Insurance Limited

36 Robinson Road #16-01

City House

Singapore (068877)

Dear Sirs,

RE: Additional Cost of repair to Yamaha T155 – FBT2007P

1pc of Magneto Cover LH	✓ BR	S\$	185.00
1pc of Double Stand	✓ BT		95.00
1pc of Clutch Cover RH	✓ CUT		190.00
1pc of Front & Rear Exhaust Cover	✓ CUT		65.00
			535.00
	Less 10%		53.50
	Nett		481.50

Yours Faithfully,
Southern Motor

Steve (LKK)
15/06/22

