

CONNECT 3
 566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com
 ROC:53360061L
 GST:53360061L

QT22/PC9333A/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,
 Cost of Repair to Vehicle PC9333A
 With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front RH rear view mirror assy (full set) / GR	1	2,250.00	2,250.00 ✓
2.	Front windscreen / CUT	1	6,800.00	6,800.00
3.	Front windscreen inner seal / NA	1	650.00	650.00 ✓
4.	Sealant / NA	8	40.00	320.00 ✓
5.	ERP bracket / NA	1	26.00	26.00 ✓
6.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00
7.	Check wiring	1	50.00	50.00
8.	Labour charges	1	400.00	400.00
9.	Spray painting with pearl paint	1	400.00	400.00
SUB-TOTAL				SS11,896.00

6300 ✓
 nett
 nett
 nett

8550
 -10%
 7695

• Price before 7% gst
 Thank you.

Yours faithfully,

Winnie Chai
 HP: 9850-9666



LIKES & COMMENTS hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without prejudice" basis
 • No charge for resurvey if it is not
 • Supplying the repairer with the necessary
 is only "NOTIFY" should the repairer require

Acknowledged by Repairer
 Signature

SPK (LKR)
 16/6/22, 11am

M R
 P/P ~~HK~~
 4 1/1

2526
 total - 10221

L/S - 8176.80
 = 8200