



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO22005705/Kty3

50 RAFFLES PLACE #03-03

Date: 15/06/2022

SINGAPORE LAND TOWERSINGAPORE 048623

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKP 3998L	Veh. Inspected	FBK 8002K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202072/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	15/06/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/06/2022	Inspection Date	16/06/2022
Survey held at	TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--