

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Celine.

China Taiping Insurance (S) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

14/6/2022

Attn: motor claims Dept

Estimate cost of repair vehicle no: GBL3564H

Tailgate *Dented*
4pcs tailgate hinge \$65x4 *2 pieces dented*
2pcs tailgate handle \$75x2 *new*
2pcs Taillamp \$378.20x2 *RH cut.*
2pcs taillamp Panel \$278.30x2 *new*
2pcs side gate lock \$270x2 *new*
2pcs side gate stopped \$38.50x2 *LH missing*
Rear exhaust pipe *new*
Rear end Panel *Repair*
Number plate panel *new*
Number plate lamp *new*
Spare tyre Holder assy *new*

1339.25 ✓
~~260.00~~ 130.
150.00 ✕
~~756.40~~ 255.
556.60 ✕
540.00 ✕
~~77.00~~ 38.50
789.10 ✕
979.20 ✕
187.90 ✕
87.90 ✕
378.20 ✕

1762.75

1322.06

S/nett items

Rear number plate *Bent*
Reverser sensor *Damaged*
Reverse sensor bracket *Bent*
70km sticker *new*
Tailgate emblem TOYOTA Sticker *new*
Tailgate emblem DYNA Sticker *new*

40.00 ✓
~~280.00~~ 200
~~60.00~~ 30
~~20.00~~ 10
~~253.40~~ 180
50.60 ✓

510.60

Labour for knocking ,welding, cutting, repairing
And replacement of parts
To spray paint on the damage parts.
To apply rust-proofing on repaired, replaced panel.
To remove/renew rear exhaust
To life up rear body for knocking cross Beam
To remove/renew reverse sensor
To check wiring

~~1200.00~~ 400
~~800.00~~ 400
~~150.00~~ 40
100.00 ✕
800.00 ✕
~~100.00~~ 50
~~60.00~~ 30

920

Total: 2752.66 Adnan Lg
4/5: 2021 1/5 15/06/22.
04 Days.