



# JACK CARS

DRIVE WITH ASSURANCE

## ESTIMATE

|                                |
|--------------------------------|
| DATE OF ACCIDENT : 09/06/2022  |
| VEHICLE : SKJ9292M             |
| MAKE & MODEL : TOYOTA VELLFIRE |
| INSURANCE : CHINA TAIPING      |
| SURVEYOR : LKK                 |

| PARTS |                                     | AMOUNT  |
|-------|-------------------------------------|---------|
| 1.    | REAR BUMPER / Re                    | \$ 1800 |
| 2.    | REAR BUMPER INNER BRACKET ?         | \$ 70   |
| 3.    | REAR BOOT / Bnc                     | \$ 2300 |
| 4.    | REAR BOOT INNER COVER ?             | \$ 380  |
| 5.    | REAR BOOT WEATHERSTRIP / Tri        | \$ 320  |
| 6.    | REAR BOOT CHROME GARNISH / SCR.     | \$ 210  |
| 7.    | REAR END PANEL ?                    | \$ 550  |
| 8.    | REAR END PANEL TOP COVER / Re       | \$ 180  |
| 9.    | RIGHT TAILGATE LAMP - INNER ? ✓ CRA | \$ 930  |
| 10.   | RIGHT TAILGATE LAMP - OUTER X NN    | \$ 650  |
| 11.   | LEFT TAILGATE LAMP - INNER R ✓ CRA. | \$ 930  |
| 12.   | LEFT TAILGATE LAMP - OUTER X NN     | \$ 650  |
| 13.   | BOOT LOCK - UPPER ?                 | \$ 320  |

|     |                                                                                                                                 |             |
|-----|---------------------------------------------------------------------------------------------------------------------------------|-------------|
| 14. | BOOT LOCK - LOWER X NN                                                                                                          | \$ 180      |
| 15. | TOW HOOK COVER / De                                                                                                             | \$ 90       |
|     |                                                                                                                                 |             |
|     | <b>SPECIAL NETT</b>                                                                                                             |             |
| 1.  | REAR NUMBER PLATE & COVER / BT                                                                                                  | \$ 65       |
| 2.  | CLIPS , RIVETS & SCREWS / MBL                                                                                                   | \$ 150      |
| 3.  | REVERSE SENSOR ?                                                                                                                | \$ 220      |
| 4.  | "VELLFIRE" EMBLEM ✓                                                                                                             | \$ 150      |
| 5.  | WINDSCREEN SEALANT / MBL                                                                                                        | \$ 120      |
| 6.  | REAR END PANEL SEALANT ?                                                                                                        | \$ 120      |
| 7.  | WINDSCREEN WEATHERSTRIP ?                                                                                                       | \$ 210      |
|     |                                                                                                                                 |             |
|     | <b>LABOUR</b>                                                                                                                   |             |
| 1.  | TO PUTTY & SPRAY PAINT OF AFFECTED AREA                                                                                         | \$ 1500 600 |
| 2.  | TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS. | \$ 2500 400 |
| 3.  | TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE                                                                                       | \$ 350 30   |
| 4.  | TO REMOVE AND REINSTALL TAILGATE COMPONENTS                                                                                     | \$ 220 60   |
| 5.  | TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY                                                                                    | \$ 280      |
| 6.  | TO REMOVE & REINSTALL SENSORS                                                                                                   | \$ 200 40   |
| 7.  | TO REMOVE & REINSTALL REAR WINDSCREEN                                                                                           | \$ 200 120  |
| 8.  | ANTI RUST TREATMENT                                                                                                             | \$ 200 60.  |
|     |                                                                                                                                 |             |



# JACK CARS

DRIVE WITH ASSURANCE

|  |                |             |
|--|----------------|-------------|
|  | PARTS - 25%:   | \$ 7,170    |
|  | SPECIAL NETT : | \$ 1,035    |
|  | LABOUR :       | \$ 5,450    |
|  | TOTAL :        | \$ 13,655   |
|  | 7% GST :       | \$ 955.85   |
|  | GRAND TOTAL :  | \$14,610.85 |

5 Days.

~~Emp, can Repair~~ P/P.

before/After repair photos

Emo@icorp - 82880282

12/7/22.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items are to be surveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: