



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22005712/Ecy3e2	
			Date: 05/10/2022	
			Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SBS 6403H
	Policy No.	D-19094584MFBP	Coverage (\$)	0.00
	Claim No.	D21002039MFBP	Excess (\$)	50,000.00
	Assign From	HARMINDER KAUR	Assign Date	15/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CITARO	c.c	6374
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WEB62808323125102	Colour	GREEN
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
	R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	4/4 mm
	L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	4/4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY, FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/07/2021	Inspection Date	16/06/2022
	Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			