

SJS637SK

TREQ.

Xiao Chen

Honda Civic

JHMFD16309S202226

Front Number Plate	} NP on	30(SN) X
Front Number Plate Holder		30(SN) X
Front Number Plate Garnish		63.10 +
Front Bumper Deformed		638.40 ✓
Front Bumper Clips. New		30(SN) ✓
Front Bumper Side Holder RH. Dented		25.10. ✓
Front Bumper Reinforcement. NP on		258.10 X
Front Bumper Fog Lamp RH. Cracked		225.10. ✓
Front Bumper Fog Lamp Cover RH. NP on		65.40 X
Front Grille. Cracked		224.60 ✓
Front Grille Clips. } New		20(SN) ✓
Front Grille Logo		A3.80 ✓
Front Grille Chrome Moulding NP over		185.30 X
Headlamp RH. Cracked		912.10 ✓

SJS 6375K.

Headlamp Lower Bracket RH. Bert	49.10	✓
Bonnet Buckle	606.20	✓
Bonnet Lock. New	85.40	+
Front Support Panel Top Cover Behind	92.60	✓
Front Support Panel Top Cover Clips. New	20(SN)	✓
Front RH Fender. Dented	537.50	✓
Front RH Fender Lower Shield Torn	165.50	✓
Front RH Fender Lower Shield Clips. New	30(SN)	✓

3520 SN: 100

2816

SJS6375K.

Panel Beating,  
Spray Painting,  
Wiring.  
To spray buff coat.

~~800~~ 600

~~800~~ 600

~~50~~ 30

~~150~~ 50

1280.

total: 4196.

L/S: 3.3k.

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: