

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>dismantle photo</i>	963.50	-20.00	770.80 <i>ok</i>
2	1	REAR BUMPER BRACKET LH	53.50	-20.00	42.80 <i>Run</i>
3	1	REAR BUMPER REFLECTOR LH	156.00	-20.00	124.80 <i>Run</i>
4	1	REAR SIDE BUMPER LH	325.10	-20.00	260.08 <i>Run</i>
5	1	REAR TAILGATE	<i>997.30</i> 1,200.50	-20.00	960.40 <i>Run</i>
6	1	REAR TAILGATE INNER BOARD	435.00	-20.00	348.00 <i>Run</i>
7	1	REAR TAILGATE VEZEL EMBLEM	65.00	-20.00	52.00 <i>ok</i>
8	1	REAR TAILGATE LOGO	55.00	-20.00	44.00 <i>ok</i>
9	1	REAR TAILGATE LOCK	198.50	-20.00	158.80 <i>X</i>
10	1	REAR TAILGATE REFLECTOR LH	245.30	-20.00	196.24 <i>Run</i>
11	1	REAR TAILGATE HINGES LH	65.00	-20.00	52.00 <i>Run</i>
12	1	REAR TAILGATE HINGES RH	65.00	-20.00	52.00 <i>Run</i>
13	1	REAR TAILLAMP LH	550.00	-20.00	440.00 <i>Run</i>
14	1	REAR TAILLAMP LOWER PANEL LH	335.00	-20.00	268.00 <i>Run</i>
15	1	REAR END PANEL	530.70	-20.00	424.56 <i>Run</i>
16	1	REAR END PANEL INNER GARNISH	153.70	-20.00	122.96 <i>Run</i>
17	1	REAR FENDER LH	950.90	-20.00	760.72 <i>Run</i>
18	1	REAR FENDER INNER TRIM BOARD LH	570.00	-20.00	456.00 <i>Run</i>
19	1	REAR SPARE TYRE COMPARTMENT	1,130.00	-20.00	904.00 <i>Run</i>
20	1	REAR TAILGATE RUBBER	170.00	-20.00	136.00 <i>Run</i>
21	1	REAR SMART KEYLESS SENSOR	268.50	-20.00	214.80 <i>Run</i>
Total Parts (\$\$)					6,788.96 <i>2122.60</i>
					<i>20% 1698.08</i>

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	45.00	0.00	45.00 <i>Run</i>
2	1	REAR BUMPER CLIPS (1 SET)	45.00	0.00	45.00 <i>30%</i>
3	1	REAR BUMPER SENSORS (1 SET)	260.00	0.00	260.00 <i>200X Run</i>
4	1	REAR TAILGATE INNER BOARD CLIPS (1 SET)	45.00	0.00	45.00 <i>Run</i>
5	1	REAR WINDSCREEN SEALANT	60.00	0.00	60.00 <i>ok</i>
Sub Total (\$\$)					455.00 <i>890</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 <i>30</i>
2	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>50X Run photo</i>
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>60</i>
4	1	To Dismantle and Refit Rear Windscreen Glass.	120.00	0.00	120.00 <i>ok</i>
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>30</i>
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power	1,800.00	0.00	1,800.00 <i>500</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		tools.			
Gross Labour Cost (\$\$)					2,230.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	0.00	50.00 30
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00 30
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,500.00	0.00	1,500.00 500 1300
Gross Labour Cost (\$\$)					1,610.00

< END OF ESTIMATES >

1698.08
 90
 1300

 3088.08
 41842450
 4 days #

Taufik 97495749 / 62563561
 'up' 17/6/22 @ 1140
 = 4 days
 Taufik @ Khanb.com
 L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: