




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 70622

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 07.06.2022

Low Siew Mui

Blk 273 Tampines St. 22 #10-60

Singapore 520273.

Mitsubishi Attrage 1.2 CVT

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Repair Cost for Motor Vehicle Reg. No: SMT 4265 S

1 Pc. Rear Boot <i>Rebuilt</i>		799.00	✓
1 Pc. Rear Boot Spoiler <i>HN</i>		503.00	X
2 Pcs. Rear Boot Hinger <i>HN</i>	@ 190.00	380.00	X
1 Pc. Rear Boot Chrome <i>mondy crack</i>		328.00	✓
1 Pc. Rear Boot Logo <i>HN</i>		49.00	✓
1 Pc. Attrage Emblem <i>HN</i>		38.00	✓
1 Pc. MIVEE Emblem <i>HN</i>		38.00	✓
1 Pc. Cycle Logo <i>HN</i>		20.00	✓
1 Pc. Rear Boot Lock <i>st / Dem</i>		216.00	✓ 165.00
1 Pc. Rear Weather Slip <i>damaged</i>		178.00	✓ 155.00
1 Pc. Rear End Panel <i>Rebuilt</i>		550.00	✓ 525.00
2 Pcs. Rear Lamp <i>crack / mondy crack</i>	@ 298.00	596.00	✓
2 Pcs. Rear Lamp Panel <i>HN</i>	@ 191.00	382.00	X
1 Pc. Rear Bumper <i>Rebuilt</i>		759.00	✓ 660.00
2 Pcs. Rear Bumper Side Retainer <i>broken mondy</i>	@ 50.00	100.00	✓ 60.00
2 Pcs. Rear Bumper Corner Garnish <i>HN</i>	@ 31.00	62.00	X
10 Pcs. Rear Bumper Clips <i>HN</i>	@ 5.00	50.00	✓ 20/- SH
1 Pc. Rear Bumper Lock Spoiler <i>Rebuilt</i>		799.00	✓ 600.00
1 Pc. Rear Bumper Reinforcement <i>HF</i>		399.00	X
1 Set Rear Parking Sensor <i>Dem</i>		385.00	✓ 220/- SH
1 Pc. Spare Tyre Board <i>HN</i>		611.00	X
1 Pc. Rear RH Fender <i>Repair</i>		785.00	X
1 Pc. Rear RH Fender Air Dust <i>HN</i>		59.00	X
1 Pc. Rear Panel Garnish <i>mondy damaged</i>	<i>1 pc - HN</i>	295.00	✓ 186.40
2 Pcs. Rear No. Plate Lamp <i>1 pc mondy broken</i>	@ 38.00	76.00	✓
1 Pc. Rear No. Plate & Box <i>HN</i>		60.00	X
1 Pc. Rear Camera <i>HN</i>		399.00	X
1 Pc. Rear Windscreen Inner Seal <i>HN</i>		59.00	X
1 Pc. Rear Windscreen Sealant <i>HN</i>		80.00	X

List

SH 240.00

Total (Panels / Parts):

9,055.00 (SGD)

4257.40

Page 1 of 2

10% 1070 4230 nnt

10% 3831.66




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit wiring & check wiring for all lighting & Install parking sensor.	180.00 40/-
To remove & refit interior garnish, carpet & all accident Affected area.	180.00 80/-
To remove & refit rear windscreen.	180.00 40/-
To knocking, welding, straightening, repair & renew All accident damage parts.	1,300.00 800/- 1760.00
To respray painting on all accident inner, outer accident Affected area.	1,600.00 800/-
To rust proof all accident damaged affected area.	120.00 40/-
To remove & refit, renew rear exhaust.	150.00 40/-

Total (Labor Charges): 3,710.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS	9,055.00
LABOR CHARGES	3,710.00

Grand Total: 12,765.00 (SGD)

We shall be glad if you can forward the payment at your early convenience.

**For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E**

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.