



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 1200C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER FASCIA	REPAIRED SEE LABOUR	1,500.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	771.13	-
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	90.00	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	95.00	-
1	FRONT BUMPER PROTECTOR LH	NOT NECESSARY	160.00	-
1	FRONT BUMPER PROTECTOR CHROME	NOT NECESSARY	95.00	-
10	FRONT BUMPER CLIP	SERVICEABLE	30.00	-
1	FRONT BUMPER CENTRE AIR GRILLE	NOT NECESSARY	125.00	-
1	FRONT BUMPER HEADLAMP NOZZLE	NOT NECESSARY	145.00	-
1	FRONT BUMPER HEADLAMP NOZZLE COVER	NOT NECESSARY	70.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	120.00	-
1	FRONT FOG LAMP LH	NOT NECESSARY	280.00	-
1	FRONT FOG LAMP COVER LH	SERVICEABLE	75.00	-
1	FRONT HEADLAMP LH	NOT NECESSARY	2,400.00	-
1	BONNET	REPAIRED SEE LABOUR	2,861.00	-
1	BONNET LOGO "BMW"	REPLACED	58.85	58.85
1	REAR NUMBER PLATE GARNISH	REPLACED	75.00	75.00
			8,950.98	133.85
<u>SPECIAL NETT ITEMS</u>				
2	FRONT BUMPER PARKING SENSOR (SN)	SERVICEABLE	760.00	-
1	FRONT NUMBER PLATE (SN)	REPLACED	45.00	40.00
			805.00	40.00
<u>LABOUR</u>				
TO STRAIGHTEN AND PANEL BEATING BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH AND FRONT LH FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER FASCIA AND BONNET.			1,200.00	500.00
TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.			1,200.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	40.00
	TO ANALYSIS AND RESET ELECTRICAL MODULE SYSTEM.		380.00	180.00
			2,860.00	1,220.00
GRAND TOTAL			12,615.98	1,393.85
RECOMMENDED COST OF REPAIRS				1,393.85

Report Ref No. CS/LAW22005732/Dvce2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.