



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW22005732/Dvce2	
			Date: 03/08/2022	
			Code: L041	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SLF 8031J	Veh. Inspected	SJZ 1200C
	Policy No.		Coverage (\$)	0.00
	Claim No.	SS/sm/2021000465.Sompo (mpdi)	Excess (\$)	0.00
	Assign From	Vithyanagan (Mr.)	Assign Date	14/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 730LI	c.c	2996
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	WBAHN22010DE96707	Colour	WHITE
	Odometer	129291 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R20	BRIDGESTONE	5 mm
	L/H Front Tyre	245/40 R20	BRIDGESTONE	5 mm
	R/H Rear Tyre	275/35 R20	BRIDGESTONE	5 mm
	L/H Rear Tyre	275/35 R20	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	31/12/2019	Inspection Date	20/06/2022
	Survey held at	PRECISION MOTORWORKS PTE LTD 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB SINGAPORE 417896		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	