



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22005735/Kty3	
			Date: 16/06/2022	
			Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBE 5390R		Veh. Inspected	GX 4054J
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2202073/AGC		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	16/06/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	13/06/2022		Inspection Date	17/06/2022
Survey held at	KWEE SENG MOTOR LTD BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-353 SINGAPORE 689538			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				