




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22005735/Kty3m4 Date: 20/06/2022 Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		GBE 5390R	Veh. Inspected		GX 4054J
Policy No.			Coverage (\$)		0.00
Claim No.		CMTD2202073/AGC	Excess (\$)		0.00
Assign From		GRACE TEO	Assign Date		16/06/2022
2. Vehicle Particulars & Condition					
Make & Model		TOYOTA DYNA (M)	c.c		2986
Engine No.		HIDDEN	Year of Reg.		2004
Chassis No.		JTFUF34Y803002344	Colour		SILVER
Odometer		450080 KM	Steering		IN ORDER
Brakes		IN ORDER	Modification		NIL
General		GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185 R15X8	FALKEN	9 mm	
	L/H Front Tyre	185 R15X8	FALKEN	9 mm	
	R/H Rear Tyre	155 R12X8 (D)	FALKEN	1/1 mm	
	L/H Rear Tyre	155 R12X8 (D)	FALKEN	1/1 mm	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.					
5. General Information					
Accident Date		13/06/2022	Inspect Date / Time		17/06/2022 (01:30 PM)
Survey held at		KWEE SENG MOTOR LTD BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-353 SINGAPORE 689538			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days		

Report Ref No. CS3/SMO22005735/Kty3m4

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.