

ASS. REC. BY: Taufik

REF: CC4/GRB22005736/Tg93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 435K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKL 6702A Yr Regn: 2013 DEC

Type: M / Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Wish c.c. 1798

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 351526 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD662aw 20J000571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim, or _____

Tyre Size: F: 195/65R15

R: u

BS / (M) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 17/6/22

Survey held at JEW

Des. of Damages: (R) / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / I.S.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL _____

J.E.W MOTORS PTE LTD

Address: 60 Jalan Lam Huat, #03-72
CARROS CENTER, Singapore 737869

Repair Quotation

Vehicle number: SKL6702A
Model and make: Toyota Wish
Chassis number: JTDGG20W20J000571

Insurance company:

No.	Spare parts	Qty	Amount
1	Tailgate	1	\$ 1,504.30 <i>bt</i>
2	Tailgate windscreen glass lower rubber moulding	1	\$ 43.20 <i>ac</i>
3	Tailgate windscreen glass upper rubber moulding	1	\$ 43.10 <i>ac</i>
4	Tailgate windsceeen glass RH side rubber moulding	1	\$ 39.80 <i>ac</i>
5	Tailgate windsceeen glass LH side rubber moulding	1	\$ 39.80 <i>ac</i>
6	Tailgate "Valvematic" emblem	1	\$ 55.60 <i>ac</i>
7	Tailgate centre emblem	1	\$ 73.10 <i>ac</i>
8	Tailgate centre chrome moulding	1	\$ 302.10 <i>ac</i>
9	Tailgate centre chrome moulding clips	1set	\$ 40.00 <i>ac</i>
10	Tailgate lock	1	\$ 456.20 <i>bt</i>
11	Tailgate lock catch	1	\$ 53.20 <i>X</i>
12	Tailgate inner trim board	1	\$ 523.60 <i>ac</i>
13	Tailgate inner trim board clips	1set	\$ 50.00 <i>ac</i>
14	Tailgate opener switch button sensor	1	\$ 132.80 <i>X</i>
15	Tailgate RH lamp	1	\$ 342.80 <i>ac</i>
16	Tailgate RH lamp gasket	1	\$ 35.90 <i>ac</i>
17	Tailgate LH lamp	1	\$ 342.80 <i>X</i>
18	Tailgate LH lamp gasket	1	\$ 35.90 <i>X</i>
19	Tailgate weatherstrip	1	\$ 366.40 <i>at</i>
20	Tailgate wiper motor	1	\$ 509.70 <i>X</i>
21	Tailgate RH number plate lamp	1	\$ 78.90 <i>X</i>
22	Tailgate LH number plate lamp	1	\$ 78.90 <i>X</i>
23	Tailgate RH absorber stay	1	\$ 215.00 <i>X</i>
24	Tailgate LH absorber stay	1	\$ 215.00 <i>X</i>
25	Rear bumper	1	\$ 712.30 <i>ac</i>
26	Rear bumper clips	1set	\$ 60.00 <i>ac</i>
27	Rear bumper RH reverse sensor holder	1	\$ 45.60 <i>X</i>
28	Rear bumper RH reverse sensor	1	\$ 235.10 <i>X</i>
29	Rear bumper LH reverse sensor holder	1	\$ 45.60 <i>X</i>
30	Rear bumper LH reverse sensor	1	\$ 235.10 <i>X</i>
31	Rear bumper RH reflector	1	\$ 72.10 <i>ac</i>
32	Rear bumper LH reflector	1	\$ 72.10 <i>X</i>
33	Rear bumper RH bracket	1	\$ 55.80 <i>ac</i>
34	Rear bumper LH bracket	1	\$ 55.80 <i>X</i>
35	Rear bumper RH side retainer	1	\$ 101.40 <i>ac</i>
36	Rear bumper LH side retainer	1	\$ 101.40 <i>X</i>

37	Rear bumper RH side bracket	1	\$	68.00 X
38	Rear bumper LH side bracket	1	\$	68.00 X
39	RH taillamp	1	\$	556.90 <i>an</i>
40	RH taillamp gasket	1	\$	44.50 <i>de</i>
41	RH taillamp panel	1	\$	172.30 <i>Ry</i>
42	LH taillamp	1	\$	556.90 X
43	LH taillamp gasket	1	\$	44.50 X
44	LH taillamp panel	1	\$	172.30 X
45	End panel	1	\$	567.30 <i>bt</i>
46	End panel inner garnish	1	\$	298.00 <i>de</i>
47	End panel inner garnish clips	1set	\$	45.00 <i>zone</i>
48	End lower panel	1	\$	386.00 X
49	End panel antenna sensor	1	\$	198.30 X
50	Rear RH fender	1	\$	963.90 <i>bt</i>
51	Rear RH fender glass with rubber seal	1	\$	525.00 X
52	Rear RH fender inner trim	1	\$	768.30 <i>ow</i>
53	Rear RH fender inner trim clips	1set	\$	60.00 <i>zone</i>
54	Rear RH fender splash shield	1	\$	132.00 X
55	Rear RH fender splash shield clips	1ser	\$	30.00 X
56	Rear RH fender inner air duct	1	\$	146.00 X
57	Rear LH fender inner trim	1	\$	768.30 X
58	Rear LH fender inner trim clips	1set	\$	60.00 X
59	Rear LH fender splash shield	1	\$	132.00 X
60	Rear LH fender splash shield clips	1set	\$	30.00 X
61	Rear compartment panel trim garnish	1	\$	453.20 <i>ow</i>
62	Rear compartment panel trim board cover	1	\$	718.90 <i>de</i>
63	Spare tyre carriage	1	\$	377.50 X
64	Exhaust silencer	1	\$	1,109.30 <i>bt</i>
65	Exhaust silencer gasket	1	\$	109.80 <i>ne</i>
66	Exhaust silencer rubber mountings	3	\$	126.00 X

	\$	17,058.60
less parts 25%	\$	4,264.65
Total	\$	12,793.95

No.	Spare parts	Qty	Special Nett
1	Tailgate windscreen glass sealant	1	\$ 80.00 <i>zone</i>
2	Tailgate windscreen glass inner seal	1	\$ 60.00 <i>zone</i>
3	Tailgate reverse camera	1	\$ 850.00 X
4	RH rear fender glass sealant	1	\$ 70.00 <i>zone</i>
5	RH rear fender glass inner seal	1	\$ 50.00 X
6	RH rear fender joint sealant	1	\$ 70.00 X
7	Rear bumper reverse sensor	1set	\$ 350.00 <i>zone</i>
8	Rear number plate	1	\$ 80.00 <i>AST</i>

LABOUR

1	Labour charges to provide workmanship cut / weld and replacing of parts	\$	1,800.00	1000
2	Spray paint on affected and consistent areas	\$	1,500.00	1000
3	Check wiring and lighting system	\$	100.00	30
4	Apply rust chemical on affected areas	\$	120.00	30
5	Remove and refit tailgate windscreen glass for repair	\$	220.00	120
6	Remove and replace tailgate reverse camera for repair	\$	180.00	30
7	Remove and replace tailgate inner components for repair	\$	220.00	60
8	Remove and replace rear bumper reverse sensors for repair	\$	100.00	30
9	Remove and replace rear inner garnish and trims for repair	\$	280.00	60
10	Remove and replace exhaust silencer and gasket for repair	\$	180.00	60

Taylor 9741 5744
WP 17/6/22 @ 4:40pm
c/s Resurvey after repair
@ Felays

Total: \$ 19,103.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1401
Vehicle Details	
Vehicle No.:	SKL6702A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	WISH CVT
Primary Colour:	Orange
Manufacturing Year:	2013
Engine No.:	2ZR1324081
Chassis No.:	JTDGG20W20J000571
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,453.00
Original Registration Date:	11 Dec 2013
First Registration Date:	11 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$19,835.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2023
PARF Rebate Amount:	\$10,909.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$73,010.00
COE Rebate Amount:	\$10,863.00
Total Rebate Amount:	\$21,772.00

The information contained herein is correct as at 13 Jun 2022

OK