

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

DATE : 30.05.2022

VEHICLE NO : **PC8973J**
MODEL : TOYOTA HIACE(HIGHROOF)
DATE OF ACCIDENT : 29.05.2022
TIME OF ACCIDENT : 08 55 AM

TP Chin-
Xiao Tong.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL RH <i>Buckled</i>	1	\$ 1,987.60	\$ 1,987.60
2	REAR SIDE INNER PANEL RH <i>Rejs</i>	1	\$ 1,620.00	\$ 1,620.00
3	REAR SIDE INNER LOWER PANEL RH	1	\$ 659.30	\$ 659.30
4	REAR SIDE INNER LOWER CORNER PANEL RH <i>Rejs</i>	1	\$ 887.30	\$ 887.30
5	REAR SIDE PANEL INNER TRIM RH <i>crushed</i>	1	\$ 345.60	\$ 345.60
6	REAR SIDE PANEL AIR VENT RH <i>Rejs</i>	1	\$ 95.30	\$ 95.30
7	REAR BUMPER <i>Rejs</i>	1	\$ 598.60	\$ 598.60
8	REAR BUMPER BRACKET <i>Rejs</i>	1	\$ 28.60	\$ 28.60
9	REAR BUMPER SIDE RETAINER <i>Rejs</i>	1	\$ 72.60	\$ 72.60
10	TAIL LAMP <i>crushed</i>	1	\$ 398.60	\$ 398.60
11	TAILLAMP PANEL RH <i>Rejs</i>	1	\$ 594.90	\$ 594.90
12	TAILLAMP INNER PANEL RH <i>Rejs</i>	1	\$ 587.10	\$ 587.10
13	TAILLAMP LOWER GARNISH <i>Rejs</i>	1	\$ 205.60	\$ 205.60
14	TAILLAMP LOWER GARNISH RETAINER <i>Rejs</i>	1	\$ 69.80	\$ 69.80
15	TAILGATE <i>Rejs</i>	1	\$ 2,103.60	\$ 2,103.60
16	TAILGATE DETECTOR <i>Rejs</i>	1	\$ 398.70	\$ 398.70
17	TAILGATE DETECTOR WIRE HARNESS <i>Rejs</i>	1	\$ 587.40	\$ 587.40
18	TAILGATE LOGO <i>Rejs</i>	1	\$ 75.20	\$ 75.20
19	TAILGATE INNERLOCK <i>Rejs</i>	1	\$ 498.60	\$ 498.60
20	TAILGATE LOCK CATCH <i>Rejs</i>	1	\$ 58.20	\$ 58.20
21	TAILGATE EMBELM 'G.L.' <i>Rejs</i>	1	\$ 54.10	\$ 54.10
22	TAILGATE EMBELM 'HIACE'	1	\$ 73.60	\$ 73.60
23	TAILGATE CENTER MOULDING (CHROME) <i>Rejs</i>	1	\$ 674.80	\$ 674.80
24	TAILGATE OUTER HANDLE <i>Rejs</i>	1	\$ 398.10	\$ 398.10
25	TAILGATE CORNER INNER GARNISH <i>Rejs</i>	1	\$ 39.80	\$ 39.80
26	TAILGATE STOPPER <i>Rejs</i>	1	\$ 28.00	\$ 28.00
27	TAILGATE INNER TRIM <i>Rejs</i>	1	\$ 298.60	\$ 298.60
28	TAILGATE WEATHERSTRIP <i>Rejs</i>	1	\$ 398.60	\$ 398.60
29	REAR END PANEL (INNER) <i>Rejs</i>	1	\$ 1,043.20	\$ 1,043.20
30	REAR END PANEL (OUTER) <i>Rejs</i>	1	\$ 598.40	\$ 598.40

VEHICLE NO : PC8973J
 MODEL : TOYOTA HIACE(HIGHROOF)
 DATE OF ACCIDENT : 29.05.2022
 TIME OF ACCIDENT : 08 55 AM

31	REAR END PANEL (EXTEND) RH <i>Rejis</i>	1	\$ 497.70	\$ 497.70	<i>X</i>
32	REAR END PANEL TOP GARNISH <i>Neu</i>	1	\$ 298.60	\$ 298.60	<i>+</i>
33	REAR END INNER SUPPORT MEMBER RH <i>Rejis</i>	1	\$ 426.80	\$ 426.80	<i>+</i>
34	REAR SILENCER BOX <i>Neu</i>	1	\$ 698.70	\$ 698.70	<i>+</i>

5299.80
3974.85

TOTAL PRICE \$ 17,501.60
 LESS 25% \$ 4,375.40
SUB TOTAL PRICE \$ 13,126.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Stained</i>	1	\$ 50.00	\$ 50.00	<i>-</i>
2	REAR REVERSE SENSORS <i>Stained neu</i>	1 SET	\$ 250.00	\$ 250.00	<i>200 X</i>
3	REAR BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
4	REAR SIDE PANEL SEALANT RH <i>Neu</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
5	REAR SIDE INNER PANEL SEALANT RH <i>3 ml</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
6	REAR SIDE INNER LOWER PANEL RH SEALANT <i>1 ml</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
7	REAR SIDE PANEL INNER TRIM CLIP RH (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
8	REAR SIDE PANEL GLASS SEALANT RH <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
9	REAR SIDE PANEL GLASS INNER SEAL LH <i>Neu</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
10	TAIL LAMP CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
11	TAILLAMP PANEL SEALANT LH <i>Neu</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
12	TAILLAMP LOWER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
13	TAILGATE CENTER MOULDING 'EMERGENCY DOOR' STICKER <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
14	TAILGATE CENTER "PULL TO OPEN" STICKER <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
15	TAILGATE INNER TRIM CLIP (SET) <i>X 50 neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
16	TAILGATE WINDSCREEN SEALANT <i>3 ml</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
17	TAILGATE WINDSCREEN INNER SEAL <i>1 ml</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
18	TAILGATE STICKER '70KM/H' <i>3 ml</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
19	TAILGATE STICKER '80/90 KM/J' <i>3 ml</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
20	TAILGATE STICKER 'OSAKA TOYOTA' <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
21	REAR END PANEL (OUTER) SEALANT <i>3 ml</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
22	REAR END PANEL (INNER) SEALANT <i>1 ml</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
23	REAR END PANEL (EXTEND) SEALANT LH <i>Neu neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>

TOTAL \$ 1,870.00

370

VEHICLE NO : **PC8973J**
 MODEL : **TOYOTA HIACE(HIGHROOF)**
 DATE OF ACCIDENT : 29.05.2022
 TIME OF ACCIDENT : 08 55 AM

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,000.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	1000
3	LABOUR REMOVE STAINED PAINT	\$ 800.00	150
4	WIRNING, BULB CHECKING	\$ 200.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 650.00	80
6	TRANSFER TAILGATE MECHAISM	\$ 80.00	x
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	x
8	To spray full coat	\$ 120.00	80
9	REMOVE AND REFIX SIDE PANEL GLASS LH	\$ 200.00	100
10	REAR CHASSIS ALIGHMENT	\$ 250.00	x
11	REMOVE AND REFIX REAR REVERSE SENSORS	\$ 80.00	50

TOTAL \$ 6,500.00

0290

TOTAL PARTS COST : \$ 14,996.20
 TOTAL LABOUR COST : \$ 6,500.00
 TOTAL REPAIR COST : \$ 21,496.20

Adrian L
 1/s 01/06/22.

08 days

total: 6684.85

4/s: 5.3K

5.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party suppliers are on a "best price" basis
- No liability for damage to property
- Such work must be carried out by a qualified person
- The repairer must be a member of the LKK Auto Consultants Company

Acknowledged by Repairer
 Signature: _____
 Date: _____