



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/ASM22005747/Tvy3m4 Date: 06/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1747Y	Veh. Inspected	SLE 2748U	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M044CK	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	16/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVWZZZAUZGW338107	Colour	GREY	
Odometer	65617 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2022	Inspection Date	17/06/2022	
Survey held at	25 KAKI BUKIT ROAD 4 #01-44 SINGAPORE 417800			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	