

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON VOLKSWAGEN GOLF

VEHICLE NO : SLE2748U

DATE: 16/06/2022

PARTS DESCRIPTION

LIST ITEMS

	QTY	UNTIL PRICE	AMOUNT
1 RH FRONT DOOR	1	\$1,845.00	\$1,845.00 <i>bt 1392</i>
2 RH FRONT DOOR OUTER HANDLER	1	\$236.00	\$236.00 <i>x nn</i>
3 RH FRONT DOOR OUTER MOULDING	1	\$164.00	\$164.00 <i>x nn</i>
4 RH FRONT DOOR INNER TRIM BOARD	1	\$1,589.00	\$1,589.00 <i>cur 787</i>
5 RH FRONT DOOR INNER LOWER RUBBER	1	\$269.00	\$269.00 <i>x 7</i>
6 RH FRONT DOOR POWER WINDOW MOTOR	1	\$785.00	\$785.00 <i>x nn</i>
7 RH FRONT DOOR POWER WINDOW REGULATOR GEAR	1	\$520.00	\$520.00 <i>x }</i>
8 RH FRONT DOOR WEATHER STRIPE	1	\$298.00	\$298.00 <i>nn</i>
9 RH FRONT DOOR BLACK STICKER	1	\$212.00	\$212.00 <i>net XNS</i>
10 RH FRONT DOOR LOCK	1	\$680.00	\$680.00 <i>bt 446.50</i>
11 RH REAR DOOR	1	\$1,544.00	\$1,544.00 <i>bt 1420</i>
12 RH REAR DOOR HINGE	1	\$125.00	\$125.00 <i>x nn</i>
13 RH REAR DOOR CHECKER	1	\$118.00	\$118.00 <i>x nn</i>
14 RH REAR DOOR BLACK STICKER	1	\$212.00	\$212.00 <i>net XNS</i>
15 RH REAR DOOR WEATHER STRIPE	1	\$298.00	\$298.00 <i>net</i>
16 RH ROCKER PANEL (OUTER)	1	\$2,415.00	\$2,415.00 <i>bt 1500</i>
17 RH CENTER DOOR PILLAR PANEL (OUTER)	1	\$1,654.00	\$1,654.00 <i>x R</i>
18 RH FRONT DOOR INNER GARNISH	1	\$178.00	\$178.00 <i>de</i>
19 RH FRONT DOOR RUBBER (DOOR RIM)	1	\$112.00	\$112.00 <i>x nn</i>
20 RH FRONT DOOR STEP CHROME MOULDING	1	\$134.00	\$134.00 <i>x nn</i>

TOTAL :

\$13,388.00 \$13,388.00

LESS 10% :

\$1,338.80 \$1,338.80

TOTAL :

\$12,049.20 \$12,049.20

S/NETT ITEMS

1 RH FRONT DOOR INNER TRIM BOARD CLIPS	1	\$80.00	\$80.00 <i>20 net</i>
2 RH CENTER PILLAR INNER GARNISH CLIPS	1	\$80.00	\$80.00 <i>x nn</i>

TOTAL :

\$160.00 \$160.00

TOTAL SPARE PARTS :

\$12,209.20 \$12,209.20

SLE2748U VOLKSWAGEN GOLF

LABOUR DESCRIPTION	AMOUNT
1 LABOUR FOR PANEL BEATING	\$1,500.00 700
2 LABOUR FOR SPRAYPAINTING	\$1,400.00 800
3 LABOUR FOR REMOVE & TRANSFER BOTH RH DOORS FITTING	\$600.00 60
4 TO APPLY TUFF COAT / RUST PROOF ON ACCIDENT AREAS	\$300.00 30
5 WIRING CHECK	\$80.00 x
6 LABOUR FOR REMOVE & REFIX ROOF LINING / INNER GARNISH / CARPET	\$400.00 60
TOTAL LABOUR :	<u>\$4,280.00</u>
TOTAL PARTS AND LABOUR :	<u>\$16,489.20</u>

Tanjin 99495749
WP 17/6/22
L/S Resurvey after repair
Tanjin Chhanta.com.
06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: