

AEIS REC BY: TP

REF: CS/ASM 2200.5747/703

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SHA 1747Y**

Policy No: _____

Claims No: **S2M044CK**


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **\$69k**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **WP**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLE 27484** Yr Regn: **2016 July**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Volkswagen Golf** C.C. **1395**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **65617** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **INVW ZZZ AVZG W 338107**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/40R18**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **14/6/2022**

Survey held at **TSL Auto.**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. **6** mm

L/Bal. **6** mm

D.O.I. **17/6/22**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- No GIA report upload. - 22/2/2022 1.30pm.

2/3/23 Lump sum \$5900 confirmed by email (Red 10,589.20, 64%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) **2/3/23-typist**

Rep. Form: **TP**

Lump Sum / L.B. **LS \$5900**

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TSL AUTO GARAGE

QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON VOLKSWAGEN GOLF

VEHICLE NO : SLE2748U

DATE: 16/06/2022

PARTS DESCRIPTION

LIST ITEMS

	QTY	UNTIL PRICE	AMOUNT
1 RH FRONT DOOR	1	\$1,845.00	\$1,845.00 <i>bt 1392</i>
2 RH FRONT DOOR OUTER HANDLER	1	\$236.00	\$236.00 <i>x ny</i>
3 RH FRONT DOOR OUTER MOULDING	1	\$164.00	\$164.00 <i>x ny</i>
4 RH FRONT DOOR INNER TRIM BOARD	1	\$1,589.00	\$1,589.00 <i>cur 787</i>
5 RH FRONT DOOR INNER LOWER RUBBER	1	\$269.00	\$269.00 <i>x 7</i>
6 RH FRONT DOOR POWER WINDOW MOTOR	1	\$785.00	\$785.00 <i>x }</i>
7 RH FRONT DOOR POWER WINDOW REGULATOR GEAR	1	\$520.00	\$520.00 <i>x }</i>
8 RH FRONT DOOR WEATHER STRIPE	1	\$298.00	\$298.00 <i>net</i>
9 RH FRONT DOOR BLACK STICKER	1	\$212.00	\$212.00 <i>net XNS</i>
10 RH FRONT DOOR LOCK	1	\$680.00	\$680.00 <i>bt 496.50</i>
11 RH REAR DOOR	1	\$1,544.00	\$1,544.00 <i>bt 1420</i>
12 RH REAR DOOR HINGE	1	\$125.00	\$125.00 <i>x</i>
13 RH REAR DOOR CHECKER	1	\$118.00	\$118.00 <i>x</i>
14 RH REAR DOOR BLACK STICKER	1	\$212.00	\$212.00 <i>net XNS</i>
15 RH REAR DOOR WEATHER STRIPE	1	\$298.00	\$298.00 <i>net</i>
16 RH ROCKER PANEL (OUTER)	1	\$2,415.00	\$2,415.00 <i>bt 1500</i>
17 RH CENTER DOOR PILLAR PANEL (OUTER)	1	\$1,654.00	\$1,654.00 <i>x R</i>
18 RH FRONT DOOR INNER GARNISH	1	\$178.00	\$178.00 <i>de</i>
19 RH FRONT DOOR RUBBER (DOOR RIM)	1	\$112.00	\$112.00 <i>x</i>
20 RH FRONT DOOR STEP CHROME MOULDING	1	\$134.00	\$134.00 <i>x</i>

TOTAL :	\$13,388.00	\$13,388.00
LESS 10% :	\$1,338.80	\$1,338.80
TOTAL :	\$12,049.20	\$12,049.20

S/NETT ITEMS

1 RH FRONT DOOR INNER TRIM BOARD CLIPS	1	\$80.00	\$80.00 <i>20 net</i>
2 RH CENTER PILLAR INNER GARNISH CLIPS	1	\$80.00	\$80.00 <i>x</i>

TOTAL :	\$160.00	\$160.00
---------	----------	----------

TOTAL SPARE PARTS :	\$12,209.20	\$12,209.20
---------------------	-------------	-------------

SLE2748U VOLKSWAGEN GOLF

LABOUR DESCRIPTION	AMOUNT
1 LABOUR FOR PANEL BEATING	\$1,500.00 700
2 LABOUR FOR SPRAYPAINTING	\$1,400.00 800
3 LABOUR FOR REMOVE & TRANSFER BOTH RH DOORS FITTING	\$600.00 60
4 TO APPLY TUFF COAT / RUST PROOF ON ACCIDENT AREAS	\$300.00 30
5 WIRING CHECK	\$80.00 X
6 LABOUR FOR REMOVE & REFIX ROOF LINING / INNER GARNISH / CARPET	\$400.00 60
TOTAL LABOUR :	<u>\$4,280.00</u>
TOTAL PARTS AND LABOUR :	<u>\$16,489.20</u>

Tanjin 97495749
WP 17/6/22
4/5 Resurvey after repair
Tanjin Chhanta.com.
06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: