

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 01.06.22

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SJV6345G
MODEL : VOLKSWAGEN JETTA
DATE OF ACCIDENT : 29.05.22
TIME OF ACCIDENT : 14:40HRS

WWZ221K2A400113

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Repair</i>	1	\$ 1,502.70	\$ 1,502.70
2	BOOT LID LOGO	1	\$ 117.07	\$ 117.07
3	BOOT LID EMBLEM 'JETTA'	1	\$ 114.21	\$ 114.21
4	BOOT LID EMBLEM 'TSI'	1	\$ 89.62	\$ 89.62
5	BOOT LID LOCK <i>new</i>	1	\$ 194.71	\$ 194.71
6	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 260.33	\$ 260.33
7	BOOT LID REVERSE LAMP LH <i>could</i>	1	\$ 197.33	\$ 197.33
8	BOOT LID HINGE <i>new</i>	2	\$ 177.33	\$ 354.66
9	TAIL LAMP LH <i>could</i>	1	\$ 389.31	\$ 389.31
10	TAIL LAMP LOWER BRACKET <i>could LH</i>	2	\$ 49.75	\$ 99.50
11	REAR BUMPER (UPPER) <i>3 Debonand</i>	1	\$ 1,007.30	\$ 1,007.30
12	REAR BUMPER (LOWER)	1	\$ 674.31	\$ 674.31
13	REAR BUMPER REFLECTOR <i>LH could</i>	2	\$ 70.95	\$ 141.90
14	REAR BUMPER CENTER BRACKET <i>could</i>	1	\$ 140.40	\$ 140.40
15	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 50.99	\$ 101.98
16	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 698.51	\$ 698.51
17	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 89.42	\$ 178.84
18	REAR FENDER INNER COWLING <i>new</i>	2	\$ 180.77	\$ 361.54
19	REAR END PANEL <i>new</i>	1	\$ 961.33	\$ 961.33
20	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 207.15	\$ 207.15

TOTAL PRICE \$ 7,792.70
LESS 10% \$ 779.27
SUB TOTAL PRICE \$ 7,013.43

3275.45.
2947.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	BOOT LID SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00

30
X

TO : **LONPAC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJV6345G**
 MODEL : **VOLKSWAGEN JETTA**
 DATE OF ACCIDENT : 29.05.22
 TIME OF ACCIDENT : 14:40HRS

3	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	BOOTLID 'BABY ON BOARD' STICKER (SPECIAL TYPE) <i>new</i>	1	\$ 80.00	\$ 80.00	20
5	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
6	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
10	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	20

TOTAL \$1,040.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	400-
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	400
3	TUFF COAT	\$ 250.00	30
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X.
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	+
8	TRANSFER BOTLID MECHANISM	\$ 80.00	+
9	CONDUCT WATER LEAKAGE TEST	\$ 150.00	+
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

TOTAL \$4,020.00

ESTIMATE REPORT

TOTAL PARTS COST : \$8,053.43
 TOTAL LABOUR COST : \$4,020.00
 TOTAL REPAIR COST : \$12,073.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Plus prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Adrian Ling
H/S 02/06/22
04 Days
total: 4117.90
H/S: 3.3K