

TP Allianz.  
Hai Rong.

GBL934T 2021 March

Toyota Hiace 2982cc

JTFHT02P500251454

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

481-80.

Rear Bumper Deformed

Rear Bumper Clips. 1pc

Rear Bumper Side Holder x 02 1pc

Rear Bumper Sticker 1pc

Rear Bumper Lower Bracket x 04 Bent

Reverse sensor Damaged

Rear End Panel outer Dented.

Rear End Panel Inner Repair

Taillamp x 02 Not rec

Taillamp Lower Apron x 02 1st time

Tailgate Dented

Tailgate Lock Damaged

Tailgate Weatherstripe. 1st

Tailgate Outer Moulding 2 pc

Tailgate Outer Moulding clips 1 pc

Tailgate Camera. Damaged

30(SN) ✓

65.8 x 2 = 131.60 ✓

~~100(SN)~~ 50(SN).

25 x 4 = 100 ✓

~~280(SN)~~ 200(SN).

589.60 ✓

645.90. X

325.1 x 2 = 650.20. X. 94.20

94.2 x 2 = 188.40.

1855.20 ✓

275.40 ✓

381.90 ✓

364.70. X

20(SN) X

~~580(SN)~~ 450(SN)

GBL934T

Tailgate Glass Molding	} New	172.50	✓
Tailgate Glass Sealant		60(SN)	✓
Toyota Logo	} New	65.80	✓
Toyota Sticker		30	✓
70km/h Sticker		4178.10 3133.57	10(SN) ✓
Company Sticker		S-N 870	10(SN) ✓
Sealant	New	60(SN)	✓
Panel Beating		<del>1200</del>	80
Spray Painting		<del>1200</del>	80
Wiring		<del>50</del>	30
To remove reverse sensor	2020	<del>100</del>	50
To remove rear camera		<del>100</del>	50
To spray tuff coat		<del>150</del>	60
To remove upholstery		<del>150</del>	30
To remove tailgate glass		Total 6023.57	
To transfer tailgate fittings		N/S: 48K	<del>180</del> 120
		06 days	<del>150</del> 80
		(4.8K)	
			\$10359.10