

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 8198 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER, LHS SILL PANEL AND DOOR ENTRANCE. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00	1000
3	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, DOOR HANDLE AND DOOR ENTRANCE.	\$ 3,500.00	Fender 550 Door 550 +550 sill panel.
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	Handle x 2 = 200 1300
TOTAL LABOUR CHARGES		: \$ <u>6,592.00</u>	

Adrian
 H.S.
 Resurveyed.