



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 639P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	TO REPAIR SEE LABOUR	3,888.00	-
1	BOOT LID LOGO BADGE	NECESSARY	189.00	100.00
1	BOOT LID EMBLEM "A6"	NECESSARY	167.00	86.00
1	BOOT LID EMBLEM "TFSI"	NECESSARY	167.00	88.00
1	BOOT LID LOWER CHROME	CRACKED	601.00	601.00
1	REAR BUMPER	BROKEN	2,301.00	2,301.00
2	REAR BUMPER SIDE RETAINER LH / RH @\$101.00	NOT NECESSARY	202.00	-
1	REAR BUMPER LOWER GARNISH	CUT	389.00	389.00
1	REAR BUMPER TOWING COVER	MISSING	158.00	45.00
1	REAR REINFORCEMENT	BENT	878.00	878.00
2	REAR REVERSE SENSOR @\$245.00	SHORTED	490.00	490.00
1	END PANEL (NPA)	NOT NECESSARY	-	-
2	REAR BUMPER LOWER SIDE BRACKET LH / RH @ \$156.00 (ADDITIONAL)	BROKEN	312.00	312.00
	LESS 5% DISCOUNT		-487.10	-264.50
			9,254.90	5,025.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	35.00	30.00
			35.00	30.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF BOOT LID.		1,000.00	300.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		60.00	30.00
	TO REMOVE AND REPLACE REAR REVERSE SENSOR.		100.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIX / REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		60.00	30.00
			2,020.00	790.00
GRAND TOTAL			11,309.90	5,845.50
RECOMMENDED COST OF REPAIRS				5,845.50

Report Ref No. CS/FCI22005760/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.