

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Jun-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1687 X

1 pc	Tailgate	\$	2,292.30	h/
1 pc	Tailgate lower garnish	\$	362.61	eng
1 pc	Tailgate weatherstrip	\$	276.98	? ✓
2 pcs	Tailgate hinge @\$28.50	\$	57.00	Rx
1 pc	Tailgate lock	\$	216.48	? ✓
2 pcs	Rear license plate lamp @ \$18.60	\$	37.20	? X
1 pc	Rear windscreen glass	\$	397.90	bm ✓
1 pc	Rear windscreen moulding	\$	64.10	wey
1 pc	End panel - photo.	\$	853.85	bt
1 pc	End panel top garnish	\$	90.00	? ✓
1 pc	Floorboard compartment	\$	913.81	? X
1 pc	Emblem I30	\$	27.80	wey
1 pc	Emblem CRDI	\$	29.40	wey
1 pc	Emblem Hyundai	\$	29.40	wey
2 pcs	Tailgate n/s & o/s reflector @ \$295.10	\$	590.20	eng
2 pcs	Rear n/s & o/s tail lamp @ \$321.30	\$	642.60	n/s ? o/s eng
1 pc	Tailgate inner trim	\$	431.12	eng
1 pc	Luggage tray- Center Rr	\$	299.48	? ✓
1 pc	Rear o/s fender	\$	1,525.73	Rpx
1 pc	Rear bumper	\$	811.11	wey
1 pc	Rear bumper sponge	\$	79.20	? X
1 pc	Rear bumper reinforcement	\$	815.64	? ✓
1 pc	Rear bumper reinforcement centre	\$	79.20	? X
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40	de
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00	n/s X 107.5
		\$	11,242.51	
		Less 20%	\$	2,248.50
		\$	8,994.01	

S/NETT

1 set	Rear bumper clips	\$	48.00	30 wey
1 set	Reverse sensor	\$	280.00	200 wey
1 set	Tailgate stickers	\$	100.00	wey - 60
1 set	Tailgate lower garnish clips	\$	38.00	wey
1 set	End panel inner garnish clips	\$	38.00	?
1 set	Floorboard compartment insulator paddings	\$	120.00	?

1 pc	Rear number plate		\$	50.00	one - 45
1 set	Sealant	105	\$	50.00	30 ne -
1 pc	Rear n/s fender sticker		\$	60.00	na - 30

16-Jun-22


ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1687 X

Sundry	\$	50.00	✓
Towing Fee	\$	50.00	? how by wept
To dismantle / refit rear windscreen glass onto new tailgate	\$	120.00	✓
To dismantle and refit the inner components of wiper onto new tailgate, test wiper motor and water etc	\$	120.00	60
To dismantle and replace reverse sensor and test system	\$	80.00	30
To labour charge for dismantle and renewal of the accident damaged parts. To heat/weld & cut end panel and floorboard compartment. Including knock-out, straighten, repair, reshape of the n/s rooftop panel, etc	\$	2,200.00	1000
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard compartment, rear n/s fender, top n/s rooftop panel	\$	1,400.00	1000
To apply rustproofing on the repaired and replaced panels	\$	200.00	30
Total	\$	13,998.01	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanjin 17495747
 WP 17/6/22 e 2pm
 1/3 Reming after rep
 Tanjin @ Mr auto.com
 06 days



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL : 6743 1987 (3 LINES) FAX : 6743 0013
Email: peoplevehicle@gmail.com
Reg No: 200415052W



Date: 16-6-22

CASH/SALE/WORK ORDER No: PA 2848

Messrs: Pauto (Pte)

Vehicle No: SHD 1687 X 车型 Capudai 130

From: 538 Juong west

To: Omega Level 1

其他 1 key

Remark:

時間 11:56-12:06 AM AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

經手人 42141-4363 收貨人 4363
Authorised by: Received by:

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)