

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Jun-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1687 X

1 pc	Tailgate	\$	2,292.30 <i>bt</i>
1 pc	Tailgate lower garnish	\$	362.61 <i>cu</i>
1 pc	Tailgate weatherstrip	\$	276.98 <i>bt</i>
2 pcs	Tailgate hinge @\$28.50	\$	57.00 <i>Rx</i>
1 pc	Tailgate lock	\$	216.48 <i>bt</i>
2 pcs	Rear license plate lamp @ \$18.60	\$	37.20 <i>Rum</i>
1 pc	Rear windscreen glass	\$	397.90 <i>bm</i>
1 pc	Rear windscreen moulding	\$	64.10 <i>uq</i>
1 pc	End panel <i>photo</i>	\$	853.85 <i>bt</i>
1 pc	End panel top garnish	\$	90.00 <i>del</i>
1 pc	Floorboard compartment	\$	913.81 <i>Rum</i>
1 pc	Emblem I30	\$	27.80 <i>uq</i>
1 pc	Emblem CRDI	\$	29.40 <i>uq</i>
1 pc	Emblem Hyundai	\$	29.40 <i>uq</i>
2 pcs	Tailgate n/s & o/s reflector @ \$295.10	\$	590.20 <i>cu</i>
2 pcs	Rear n/s & o/s tail lamp @ \$321.30	\$	642.60 <i>n/s o/s cu</i>
1 pc	Tailgate inner trim	\$	431.12 <i>cu</i>
1 pc	Luggage tray- Center Rr	\$	299.48 <i>del</i>
1 pc	Rear o/s fender	\$	1,525.73 <i>Rx</i>
1 pc	Rear bumper	\$	811.11 <i>uq</i>
1 pc	Rear bumper sponge	\$	79.20 <i>Rum</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>bt</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 <i>Rum</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>del</i>
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00 <i>n/s x uq 107.5</i>
		\$	11,242.51
		\$	2,248.50
		\$	8,994.01
S/NETT			
1 set	Rear bumper clips	\$	48.00 <i>30 uq</i>
1 set	Reverse sensor	\$	280.00 <i>200 uq</i>
1 set	Tailgate stickers	\$	100.00 <i>uq - 60</i>
1 set	Tailgate lower garnish clips	\$	38.00 <i>uq</i>
1 set	End panel inner garnish clips	\$	38.00 <i>Rum</i>
1 set	Floorboard compartment insulator paddings	\$	120.00 <i>Rum</i>

8442.87
6754.30 Less 20%

328

1 pc Rear number plate
1 set Sealant
1 pc Rear n/s fender sticker

\$ 50.00 *one - 45*
\$ 50.00 *30 ne*
\$ 60.00 *na - 30*

105

16-Jun-22

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1687 X

Sundry
Towing Fee

\$ 50.00 *km*
\$ 50.00 *7 hourly*
\$ 120.00 *✓*

To dismantle / refit rear windscreen glass onto new tailgate
To dismantle and refit the inner components of wiper onto new tailgate, test wiper motor and water etc
To dismantle and replace reverse sensor and test system

\$ 120.00 *60*
\$ 80.00 *30*

To labour charge for dismantle and renewal of the accident damaged parts. To heat/weld & cut end panel and floorboard compartment. Including knock-out, straighten, repair, reshape of the n/s rooftop panel, etc

\$ 2,200.00 *1000*

To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, floorboard compartment, rear n/s fender, top n/s rooftop panel

\$ 1,400.00 *1000*

To apply rustproofing on the repaired and replaced panels

\$ 200.00 *30*

Total \$ 13,998.01 *2290*

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjin 17495747
WP 17/6/22 e 8
1/3 Reming after repair
Tanjin @ lkk auto. com
06 days

6754.30
328
505
2290
7474.30
1687550
06 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company