

TPMS16
Vercon

SNC 37685. 2021 Oct.
Honda Vezel 1496 cc
RV51009674.

Rear Number Plate.	{ NP new	30(SN) X
Rear Number Plate Holder		30(SN). X
Rear Bumper Distorted.		865.50 ✓
Rear Bumper Clips. New		30(SN). ✓
Rear Bumper Side Holder x 02	LH new	$49.3 \times 2 = 98.6$ / 4930
Rear Bumper Reflector x 02	LH new	$151.1 \times 2 = 302.2$ / 151.10
Rear Bumper lower Dehd		325.80. ✓
Rear Bumper lower Garnish (Silver) Dehd		195.90. ✓
Rear Bumper Undercover LH Dehd		145.90. ✓
Rear End Panel Distorted		595.90 ✓
Rear End Panel Top Garnish. Dehd		272.20 ✓
Rear End Panel Top Garnish Clips. New		20(SN) ✓
Rear End Panel Sealant. New		66(SN) ✓
Rear End Panel Antenna Sensor	new	196.40 ✓
Reverse Sensor x 04	2 pieces new	$164 \times 4 = 656$ / 328
Reverse Sensor Wire Harness. NP new		453.70. X

SNC 37685.

Taillap	LH.	495.40	595.40. ✓ x nn
Tailgate	Distorted	1361.20 ✓	
Tailgate Lock	Dmgd	280.40 ✓	
Tailgate Weatherstripe.	Lot	168.40. ✓	
Tailgate Outer Garnish.	Del'd	468.70 ✓	
Tailgate Outer Garnish Clips.	nr	30(SN). ✓	
Tailgate Inner Trim Board.	auth'd	298.40 ✓	
Tailgate Inner Trim Board Clips.	nr	30(SN) ✓	
Tailgate Reflector	x 02.	278.50 ✓	NE nr 986.4 x 1 = 1972.80. x
Tailgate Glass Moulding.	} for	60(SN). ✓	
Tailgate Glass Sealant.		65.40 ✓	
Honda Logo	nr	68.20. ✓	
Vetel Molding.	} nr	59.40. ✓	
Hybrid Emblem.			

5736.80

SNC 3768 S.

Rees LH Fender Rep's	1280.40 X.
Rees LH Fender Outer Arc Garnish	del'd 195.50 ✓
Rees LH Fender Outer Arc Garnish clips	new 20(SN) ✓
Rees LH Fender Inner Trim Board	del'd 399.20 ✓
Rees LH Fender Inner Trim Board clips	new 30(SN) ✓
Rees LH Fender Inner Shield torn	189.40 ✓
Rees LH Fender Inner Shield clips	new 20(SN) ✓
Rees LH Fender Inner Shield clips	
Spare Tyre Panel Top Cover.	new 557.40 X
Spare Tyre Side Panel LH. Rep's	394.20 X.
Utility Tray.	assembled 328.40 ✓
Charcoal Canister.	new new 340.20 X
Charcoal Canister Bracket. Best	65.90. ✓

3820.60

7848.40

6278.72

S.N. 300

SNC 37685.

Panel Beating

Spray Painting

Wiring.

To remove reverse sensor.

To remove rear camera.

To remove video recorder.

To spray tint coat.

To remove upholstery.

To remove tailgate g/s

To transfer tailgate fittings.

~~1800~~ 1200

~~1400~~ 1100

~~100~~ 30

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 60

~~180~~ 120

~~150~~ 80

4230

18,065.50

total: 9398.72

2/s: 7.5 K.

07 Days.

7,500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: