

TPMS16
Vercon

SNC 37685. 2021 Oct.
Honda Vezel 1496 cc
RV51009674.

Rear Number Plate.	{ NP new	30(SN) X
Rear Number Plate Holder		30(SN). X
Rear Bumper Distorted.		865.50 ✓
Rear Bumper Clips. New		30(SN). ✓
Rear Bumper Side Holder x 02	LH new	$49.3 \times 2 = 98.6$ / 4930
Rear Bumper Reflector x 02	LH new	$151.1 \times 2 = 302.2$ / 151.10
Rear Bumper lower Dehd		325.80. ✓
Rear Bumper lower Garnish (Silver) Dehd		195.90. ✓
Rear Bumper Undercover LH Dehd		145.90. ✓
Rear End Panel Distorted		595.90 ✓
Rear End Panel Top Garnish. Dehd		272.20 ✓
Rear End Panel Top Garnish Clips. New		20(SN) ✓
Rear End Panel Sealant. New		66(SN) ✓
Rear End Panel Antenna Sensor	new	196.40 ✓
Reverse Sensor x 04	2 pieces new	$164 \times 4 = 656$ / 328
Reverse Sensor Wire Harness. NP new		453.70. X

SNC 37685.

Taillap	LH.	495.40 ✓
Tailgate	Distorted	1361.20 ✓
Tailgate Lock	Dmgd	280.40 ✓
Tailgate Weatherstripe.	Lot	168.40. ✓
Tailgate Outer Garnish.	Del'd	468.70 ✓
Tailgate Outer Garnish Clips.	nr 30(SN).	✓
Tailgate Inner Trim Board.	asub'd	298.40 ✓
Tailgate Inner Trim Board Clips.	nr 30(SN)	✓
Tailgate Reflector	x 02.	NE nr 986.4 x 2 = 1972.80. x
Tailgate Glass Moulding.	} for	278.50 ✓
Tailgate Glass Sealant.		60(SN). ✓
Honda Logo	nr	65.40 ✓
Vetel Molding.	} nr	68.20. ✓
Hybrid Emblem.		59.40. ✓

5736.80

SNC 3768 S.

Rees LH Fender Rep's	1280.40 X.
Rees LH Fender Outer Arc Garnish	del'd 195.50 ✓
Rees LH Fender Outer Arc Garnish clips	new 20(SN) ✓
Rees LH Fender Inner Trim Board	del'd 399.20 ✓
Rees LH Fender Inner Trim Board clips	new 30(SN) ✓
Rees LH Fender Inner Shield torn	189.40 ✓
Rees LH Fender Inner Shield clips	new 20(SN) ✓
Rees LH Fender Inner Shield clips	
Spare Tyre Panel Top Cover.	new 557.40 X
Spare Tyre Side Panel LH. Rep's	394.20 X.
Utility Tray.	assembled 328.40 ✓
Charcoal Canister.	new new 340.20 X
Charcoal Canister Bracket. Best	65.90. ✓

3820.60

7848.40

6278.72

S.N. 300

SNC 37685.

Panel Beating

Spray Painting

Wiring.

To remove reverse sensor.

To remove rear camera.

To remove video recorder.

To spray tint coat.

To remove upholstery.

To remove tailgate glass 2820

To transfer tailgate fittings.

~~1800~~ 1200

~~1400~~ 1100

~~100~~ 30

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 60

~~180~~ 120

~~150~~ 80

4230

18,065.50

total: 9398.72

2/5: 7.5K.

07 Days.

7,500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: