

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22005766/KTY3E2

Date: 23/06/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP0001021172
Claimant Vehicle No : SNE8864D **Insured Vehicle No :** SNE3018M
Date of Loss: 15/06/2022 Nature of Claim: TP Claim No: 202222005236KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE8864D**
Make & Model: BYD E6 (ME-2), (A) Engine No: HIDDEN
Reg. Date: 19/04/2022 (Man. Year: 2022) Chassis No: LC0CE4DC2N0038854
Colour: Black Odometer: 14499 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: CHAO YANG 9 mm Rear Left Side: CHAO YANG 9 mm
Front Right Side: CHAO YANG 9 mm Rear Right Side: CHAO YANG 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,182.40	352.00	1,830.40	83.87
Miscellaneous Items	150.00	0.00	150.00	100.00
Labour	2,140.00	160.00	1,980.00	92.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,472.40	512.00	3,960.40	88.55
+ GST 7.00/7.00% (S\$)	313.07	35.84	277.23	88.55
Nett Amount (S\$)	4,785.47	547.84	4,237.63	88.55

INSPECTION

Date of Assignment: 16/06/2022 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 17/06/2022 Inspected At: Ding Auto Pte Ltd (HQ)
Estimated Period of Repair: 1.0 days 176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jun 2022)
Parts:	M1-MPV	BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE8864D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR SIDE MIRROR ASSY - RH (WCP)	Cracked	320.00 F	*320.00 F
2	1		*FRONT DOOR - RH (WCP)	Repair	1,350.00 F	*- F
3	1		*FRONT DOOR HANDLE - RH (WCP)	Serviceable	160.00 F	*- F
4	1		*DOOR UPPER HINGE (WCP)	Repair	58.00 F	*- F
5	1		*DOOR LOWER HINGE (WCP)	Repair	58.00 F	*- F
6	1		*DOOR CATCH (WCP)	Serviceable	38.00 F	*- F
F=Franchise part.						
Sub Total (\$\$)					1,984.00	320.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					198.40	32.00
Total Parts (\$\$)					2,182.40	352.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	DOOR INNER BOARD CLIPS (NOT NECESSARY)	150.00	0.00
Sub Total (\$\$)			150.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR, PANEL BEAT & ALIGN - ACCIDENT AREA	New	800.00	80.00
2	SPRAY PAINT - FRONT DOOR(RH) & DOOR SIDE MIRROR COVER	New	800.00	80.00
3	REMOVE & REFIT - DOOR COMPONENTS	New	150.00	0.00
4	REMOVE & REFIT - DOOR SIDE MIRROR COMPONENTS	New	150.00	0.00
5	ALIGN SIDE MIRROR & TEST WIRING	New	80.00	0.00
6	ALIGN DOOR HANDLE POWER WINDOW & TEST WIRING	New	80.00	0.00
7	RUST PROOFING	New	80.00	0.00
Gross Labour Cost (\$\$)			2,140.00	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >