

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLE5555P
OD/SOMPO

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2290597
Date: 17 Jun 2022
Policy No: D21MTPV01012110
Veh Reg No: SLE5555P
Make/Model: HONDA HONDA VEZEL
1.5X CVT
Chassis No: RU11202768
Engine No:
Reg. Date: 24/09/2016

WS Ref: OD SOMPO
Claim Type: Own Damage
Accident Date: 15/06/2022

Not Noted
Mewny B & Paim
3 days

Estimate Repair Cost to Vehicle No : SLE5555P

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	340.00	1 PC	340.00	✓
2 FRONT BUMPER SIDE PROTECTOR LH	10.00	1 PC	10.00	✓
3 FRONT BUMPER LOWER SKIRT	140.00	1 PC	140.00	✓
4 FRONT BUMPER CLIP	2.00	6 PCS	12.00	✓
5 FRONT LH FENDER	180.00	1 PC	180.00	✓
6 FRONT LH FENDER WHEEL ARP GARNISH	55.00	1 PC	55.00	✓
7 FRONT LH HEADLAMP	920.00	1 PC	920.00	✓
			1,657.00	
	Add 10%		165.70	1,822.70
Labour				
8 TO REMOVE AND REFIX FRT BUMPER, FRT LH FENDER, HEADLAMP; KNOCK AND REPAIR FRT BUMPER REINFORCEMENT AND RE-ALIGN TO SAME	450.00	1 LA	450.00	360
9 TO PUTTY AND RESPRAY ON FRT BUMPER, FRT LH FENDER	500.00	1 LA	500.00	800
				950.00

Total S\$ 2,772.70

Add GST @ 7% 194.09

Total Amount payable S\$ 2,966.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE