

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 661B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	91.80	91.80
1	TAILGATE	BADLY DENTED	1,177.30	1,177.30
1	TAILGATE 'PRIUS' EMBLEM	NECESSARY	72.50	72.50
1	TAILGATE 'HYBRID SYNERGY DRIVE' LOGO	NECESSARY	68.00	68.00
1	TAILGATE INNER LOCK	DENTED / DAMAGED	437.20	437.20
1	REAR BUMPER	DEFORMED / TORN	589.50	589.50
1	REAR BUMPER SIDE RETAINER N/S	BENT	89.20	89.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	TAILLAMP N/S	CRACKED	706.10	706.10
1	REAR END PANEL OUTER	BADLY DENTED	728.00	728.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	241.00	-
	LESS 25% DISCOUNT		-1,062.65	-1,002.40
			3,187.95	3,007.20
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	CRACKED	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			430.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		120.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		100.00	80.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		80.00	60.00
	TO SPRAY RUST PROOFING.		60.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		900.00	800.00

Report Ref No. CS/TP22005775/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

4,500.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,200.00	1,100.00
			2,590.00	2,290.00
	GRAND TOTAL		6,207.95	5,627.20

Report Ref No. CS/TP22005775/Uqy3e2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser