



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 REPAIR PERFORMA INVOICE

AXA

TPAXA  
 Cecilia.

|                |                   |
|----------------|-------------------|
| Vehicle number | SMY9939Y          |
| Make / Model   | HONDA CIVIC 1.5   |
| Chassis number | MRHFK4840HT000025 |
| Accident date  | 15/6/22           |
| Reference      | 2206-21           |

| Qty                                   | Particulars                                | Unit Price - SGD \$             |
|---------------------------------------|--------------------------------------------|---------------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> |                                            |                                 |
| 1                                     | BOOTLID <i>Dented</i>                      | <del>1481.59</del> <i>1150.</i> |
| 1                                     | BOOTLID EMBLEM - LOGO                      | 36.61 ✓                         |
| 1                                     | BOOTLID EMBLEM - CIVIC                     | 20.03 ✓                         |
| 1                                     | BOOTLID EMBLEM - V-TEC                     | 47.39 ✓                         |
| 1                                     | BOOTLID WEATHERSTRIP <i>cut</i>            | 181.80 ✓                        |
| 1                                     | BOOTLID LOCK <i>Jammed</i>                 | 74.61 ✓                         |
| 1                                     | BOOTLID LOCK STRIKER <i>new</i>            | 44.25 ✓                         |
| 1                                     | BOOTLID INNER TRIM <i>new</i>              | 209.24 ✓                        |
| 2                                     | TAILLAMP <i>crushed</i>                    | 995.06 ✓                        |
| 2                                     | TAILLAMP LOWER BRACKET <i>new</i>          | 202.53 ✓                        |
| 1                                     | END PANEL <i>Dented</i>                    | 738.58 ✓                        |
| 1                                     | END PANEL TOP GARNISH <i>Dented</i>        | 211.05 ✓                        |
| 1                                     | SPARE TYRE TOP BOARD <i>new</i>            | 192.80 ✓                        |
| 1                                     | SPARE TYRE TOOL SPONGE <i>new</i>          | 97.64 ✓                         |
| 1                                     | EXHAUST SILENCER <i>new</i>                | 789.64 ✓                        |
| 1                                     | EXHAUST SILENCER MOUNTING <i>new</i>       | 48.14 ✓                         |
| 1                                     | REAR BUMPER <i>Dented</i>                  | <del>2423.08</del> <i>740.</i>  |
| 2                                     | REAR BUMPER RETAINER <i>new</i>            | 85.61 ✓                         |
| 1                                     | REAR BUMPER CENTRE GARNISH <i>cut</i>      | 128.22 ✓                        |
| 1                                     | REAR BUMPER LOWER DIFFUSAL <i>cut</i>      | 199.20 ✓                        |
| 1                                     | REAR BUMPER REINFORCEMENT <i>Dented</i>    | 227.48 ✓                        |
| 2                                     | REAR BUMPER SIDE GRILLE <i>crushed</i>     | <del>622.42</del> <i>420</i>    |
| 1                                     | FRONT BUMPER <i>Dented</i>                 | <del>765.47</del> <i>680</i>    |
| 1                                     | FRONT BUMPER LOWER DIFFUSAL <i>new</i>     | 172.36 ✓                        |
| 1                                     | FRONT BUMPER LOWER LIP <i>new</i>          | 80.15 ✓                         |
| 1                                     | FRONT BUMPER TOP BRACKET <i>new</i>        | 269.83 ✓                        |
| 2                                     | FRONT BUMPER RETAINER <i>new</i>           | 35.88 ✓                         |
| 1                                     | FRONT BUMPER REINFORCEMENT <i>Dented</i>   | 434.28 ✓                        |
| 2                                     | FRONT BUMPER FOG LAMP COVER <i>crushed</i> | 355.72 ✓                        |
| 2                                     | FRONT BUMPER FOG LAMP <i>crushed</i>       | 672.98 ✓                        |
| 1                                     | FRONT GRILLE <i>crushed</i>                | 206.58 ✓                        |
| 1                                     | FRONT GRILLE EMBLEM - LOGO <i>new</i>      | 55.72 ✓                         |

|                                               |                                            |          |      |
|-----------------------------------------------|--------------------------------------------|----------|------|
| 2                                             | FRONT HEADLAMP <i>cracked</i>              | 3435.50  | 2620 |
| 2                                             | FRONT HEADLAMP BRACKET <i>cracked</i>      | 70.15    |      |
| 2                                             | FRONT HEADLAMP GARNISH <i>cracked</i>      | 188.80   |      |
| 1                                             | FRONT SUPPORT PANEL <i>rip</i>             | 600.20   |      |
| 1                                             | FRONT SUPPORT PANEL TOP GARNISH <i>new</i> | 38.36    |      |
|                                               |                                            | 16438.95 |      |
| Less 20%                                      |                                            | 3287.79  |      |
| Subtotal                                      |                                            | 13151.16 |      |
| Balance C/F                                   |                                            | 13151.16 |      |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                            |          |      |
| 1                                             | FRONT NUMBER PLATE <i>cracked</i>          | 60.00    |      |
| 1 SET                                         | FRONT BUMPER CLIP <i>new</i>               | 30.00    |      |
| 1 SET                                         | FRONT GRILLE CLIP <i>new</i>               | 30.00    |      |
| 1 SET                                         | REAR BUMPER CLIP <i>new</i>                | 30.00    |      |
| 1 SET                                         | REVERSE SENSOR <i>damaged</i>              | 250.00   |      |
| 1                                             | JOINT SEALANT <i>new</i>                   | 150.00   |      |
| Subtotal                                      |                                            | 550.00   |      |
| Balance C/F                                   |                                            | 13701.16 |      |
| S/No                                          | <u>LABOUR AND MISCELLANEOUS CHARGES</u>    |          |      |
| 1                                             | CHECK WIRING AND LIGHTINGS SYSTEM          | 120.00   | 60   |
| 2                                             | REMOVE AND REFIT TRIM AND GARNISHES        | 150.00   | 60   |
| 3                                             | REMOVE AND REFIT REAR REVERSE SENSOR       | 100.00   | 50   |
| 4                                             | REMOVE AND REFIT REAR EXHAUST ASSY         | 150.00   | x    |
| 5                                             | REMOVE AND RENEW WINDSCREEN GLASS          | 150.00   | 120  |
| 6                                             | REMOVE AND REFIT BOOTLID ATTACHMENT        | 200.00   | 60   |
| 7                                             | PANEL BEATING ON AFFECTED AREAS            | 1800.00  | 1400 |
| 8                                             | SPRAY PAINTING ON AFFECTED AREAS           | 1800.00  | 1200 |
| 9                                             | APPLY ANTI RUST ON AFFECTED AREAS          | 200.00   | 80   |
| Subtotal                                      |                                            | 4670.00  |      |
| Grand total                                   |                                            | 18371.16 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
L/S 20/06/22

10 Days

Supplementary: 857.61

Total: 12548.21

L/S: 10K

10K



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

AXA

|                |                   |
|----------------|-------------------|
| Vehicle number | SMY9939Y          |
| Make / Model   | HONDA CIVIC 1.5   |
| Chassis number | MRHFK4840HT000025 |
| Accident date  | 15/6/22           |
| Reference      | 2206-21           |

Qty Particulars

Unit Price - SGD \$

| PARTS REPLACEMENT - LIST ITEMS   |                                                           |                   |
|----------------------------------|-----------------------------------------------------------|-------------------|
| 1                                | KEYLESS ANTHENA <i>cracked</i>                            | 80.95 ✓           |
| 1                                | KEYLESS SPEAKER <i>new</i>                                | 81.09 +           |
| 1                                | TEMPERATURE SENSOR <i>new</i>                             | 98.61 +           |
| 1                                | AIRCON CONDENSER <i>Dented</i>                            | 891.07 ✓          |
|                                  |                                                           | 1151.72           |
|                                  | Less 20%                                                  | 230.34            |
|                                  | Subtotal                                                  | 921.38            |
|                                  | Balance C/F                                               | 921.38            |
| LABOUR AND MISCELLANEOUS CHARGES |                                                           |                   |
| 1                                | REMOVE & REPLACE AIRCON CONDENSER & TOP UP GAS <i>120</i> | 200.00 <i>120</i> |
|                                  | Subtotal                                                  | 200.00            |
|                                  | Grand total                                               | 1121.38           |

*Adrian L*  
*22/06/22.*  
*Slis.*

*Supplementary: 897.61*