

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Jul 2022

Preliminary Advice

Insured : GBD2378C

Vehicle No

TP Vehicle : SMX27T
No

Accident Date : 14/06/2022

Make : BMW 318i

Assignment Date : 17/06/2022

Date of : 17/06/2022

Est. Duration of : 6
Repair

Inspection

Inspection At : AKA AUTO PTE LTD (HQ)

25 KAKI BUKIT ROAD 4 #05-36 SYNERGY @ KAKI BUKIT
SINGAPORE 417800

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,281.70
Revised Amount	:S\$	10,664.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,664.30
Lump Sum Repair	:S\$	8,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.