

TP Ergo Xias Chen.



MIRAGE MOTORWERKZ PTE LTD

Main Branch

10 Kaki Bukit Road 2
#01-28/29 First East Centre
Singapore 417868
+65 6635 7111 +65 6635 7112

East Coast Branch

Shell Autoserv @ Siglap
40 Upper East Coast Road
Singapore 455212
+65 6977 7117

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No final modification(s) is allowed
- Supply of 2022 item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATED REPAIR CHECKLIST

TO :	VEHICLE REGISTRATION NO.: SMX27T
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: BMW / 318i
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: W1N2476872W034103
ACCIDENT DATE/TIME :	CONTACT PERSON :

Acknowledged by Repairer

Signature:

Date:

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 109.00	\$ 218.00
2 REAR BUMPER TOW COVER <i>new</i>	1	\$ 38.00	\$ 38.00
3 REAR BUMPER REINFORCEMENT <i>Detected</i>	1	\$ 592.00	\$ 592.00
4 REAR BUMPER REINFORCEMENT COVER <i>could</i>	1	\$ 225.00	\$ 225.00
5 REAR BUMPER CENTRE GUIDE <i>could</i>	1	\$ 192.00	\$ 192.00
6 REAR BUMPER SPONGE <i>could</i>	1	\$ 140.00	\$ 140.00
7 REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 250.00	\$ 1,000.00
8 REVERSE SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
9 REAR END PANEL <i>new</i>	1	\$ 895.00	\$ 895.00
10 REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 210.00	\$ 210.00
11 TAILLAMP <i>RH could</i>	2	\$ 550.00	\$ 1,100.00
12 BOOTLID <i>new</i>	1	\$ 1,650.00	\$ 1,650.00
13 BOOTLID LOCK <i>new</i>	1	\$ 287.00	\$ 287.00
14 BOOTLID WEATHERSTRIPE <i>new</i>	1	\$ 169.00	\$ 169.00
15 BOOTLID REFLECTOR <i>RH at</i>	2	\$ 495.00	\$ 990.00
16 BMW LOGO <i>new</i>	1	\$ 85.00	\$ 85.00
17 REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 39.00	\$ 39.00
18 REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 35.00	\$ 35.00
19 FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 95.00	\$ 190.00
20 FRONT BUMPER TOW COVER <i>new</i>	1	\$ 32.00	\$ 32.00
21 FRONT BUMPER LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
22 FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 558.00	\$ 558.00
23 FRONT BUMPER SENSOR <i>new</i>	2	\$ 250.00	\$ 500.00
24 HEADLAMP <i>RH could</i>	2	\$ 3,068.00	\$ 6,136.00
Sub total		SUBTOTAL :	\$ 14,613.00
Less 10%		LESS 10% :	\$ 1,461.30
Total List		PARTS TOTAL :	\$ 13,151.70

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>Detected</i>	1	\$ 2,000.00	\$ 2,000.00
2 REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
3 REAR BUMPER REFLECTOR <i>new</i>	2	\$ 80.00	\$ 160.00
4 REAR BUMPER LOWER DIFFUSER <i>new</i>	1	\$ 800.00	\$ 800.00
5 REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
6 REAR EXHAUST PIPE <i>new</i>	1	\$ 2,200.00	\$ 2,200.00
7 FRONT NUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00
8 FRONT NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00
9 FRONT BUMPER <i>Detected</i>	1	\$ 2,000.00	\$ 2,000.00
10 FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
11 FRONT BUMPER CENTRE GRILLE <i>RH could</i>	2	\$ 400.00	\$ 800.00
12 FRONT BUMPER SIDE GRILLE <i>new</i>	2	\$ 200.00	\$ 400.00
Sub total		S/N TOTAL :	\$ 8,580.00

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,800.00	600
2 SPRAY PAINTING	\$ 1,600.00	800
3 WIRING	\$ 100.00	60
4 TO SPRAY TUFF COAT	\$ 150.00	40
5 TO REMOVE REVERSE SENSOR	\$ 100.00	60
6 TO REMOVE UPHOLSTERY	\$ 150.00	40
7 TO TRANSFER BOOTLID FITTINGS	\$ 150.00	100
8 TO REMOVE REAR EXHAUST PIPE	\$ 150.00	100
9 TO REMOVER FRONT BUMPER SENSOR	\$ 100.00	60
10 TO PERFORM DIAGNOSTIC TEST	\$ 250.00	150
LABOR TOTAL :		\$ 4,550.00

Total 10664.30
1/2 8.5K
06 Days

8.5K