

ASS. REC. BY:

REF:

CT2/ 22005785/Kny3

C

Kenneth

ASSESSMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

Thiam Heng Hwa

of

Insured:

911N

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/

Got BT, EM not ready

21/12

11 Lm @ 4800 Cahr (Red,

\$ 15092.15, 76%)

Date/Time, File Pass to?

1) 23/12/22

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Repair:

7

Returning No. of Trip:

2

Add Fee:



Insp (\$



Flow (\$



Wmvs (\$



Kend (\$

Survey Fee:

Transportation

S + RS SI

Fines

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$

4800

Not GBD 7012A Yr Regn 03, 15

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Heavy Mover /

Truck / Trailer or

Toy Silver

Hiac

2P82

A/C:

Insured / Std / NI / NA

Loading

1P3010

T/Radio: Insured / Std / NI / NA

JTFH 702P 300156612

Cond: Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

NII / S/Rim / STD A/Rim or

F:

1P5R15x8

R:

EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

OKO or

8 mm

Rear

8 mm

R/Bal.

14/16/22

L/Bal.

D.O.I.

16/6/2022

Damage:

Frt / Rear / O/S / N/S / UIC / Rndtop or

N/S body

Chassis frame / Body Structure affected due to collision.

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Withheld

11 Bm @ 4800k

Rebody After Paint

7 days

Make/Model: TOYOTA HIACE

Engine/Chassis No.:


Date of accident:

Damaged area: N/S

Date: 16/06/2022

Claim Type: TP

VRN: GBD7012A



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper	1	\$ 754.00	\$ 754.00
2	Front bumper side retainer	2	\$ 149.60	\$ 299.20
3	Top corner panel n/s	1	\$ 485.00	\$ 485.00
4	Top corner panel garnish n/s	1	\$ 337.00	\$ 337.00
5	Head lamp n/s	1	\$ 585.00	\$ 585.00
6	Head lamp lower bracket n/s	1	\$ 42.00	\$ 42.00
7	Front door n/s	1	\$ 1,445.00	\$ 1,445.00
8	Front door inner trim board n/s	1	\$ 586.00	\$ 586.00
9	Front door window channel n/s	1	\$ 165.00	\$ 165.00
10	Front door window regulator n/s	1	\$ 287.00	\$ 287.00
11	Front door window regulator motor n/s	1	\$ 399.00	\$ 399.00
12	Front door weatherstrip n/s	1	\$ 185.00	\$ 185.00
13	Front door lower seal n/s	1	\$ 140.00	\$ 140.00
14	Front door pillar outer n/s	1	\$ 765.00	\$ 765.00
15	Front door hinge n/s	2	\$ 116.00	\$ 232.00
16	Front fender n/s	1	\$ 1,156.00	\$ 1,156.00
17	Front fender cowling n/s	1	\$ 182.00	\$ 182.00
18	Sliding door n/s	1	\$ 2,245.00	\$ 2,245.00
19	Sliding door inner trim board n/s	1	\$ 586.00	\$ 586.00
20	Fuel tank door	1	\$ 465.00	\$ 465.00
21	Sliding door hinge roller upper n/s	1	\$ 286.00	\$ 286.00
22	Sliding door hinge roller lower n/s	1	\$ 286.00	\$ 286.00
23	Sliding door weatherstrip n/s	1	\$ 185.00	\$ 185.00
24	Sliding door lower seal n/s	1	\$ 140.00	\$ 140.00
25	Rear body panel roller rail n/s	1	\$ 765.00	\$ 765.00
26	Sliding door step panel garnish n/s	1	\$ 356.00	\$ 356.00
27	Sliding door step panel n/s	1	\$ 552.00	\$ 552.00
28	Rear panel n/s	1	\$ 1,395.00	\$ 1,395.00
29	Wing mirror assy n/s	1	\$ 694.00	\$ 694.00
30	Front wheel knuckle n/s	1	\$ 374.00	\$ 374.00

SVC

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

31	Front wheel knuckle bearing n/s	1	\$ 166.00	\$ 166.00
32	Front shock absorber n/s	1	\$ 415.00	\$ 415.00
33	Front shock absorber mounting n/s	1	\$ 97.00	\$ 97.00
34	Front door outer handle n/s	1	\$ 139.00	\$ 139.00
35	Front door lock n/s	1	\$ 285.00	\$ 285.00
36	Front door lock striker n/s	1	\$ 45.00	\$ 45.00
37	Sliding door outer handle n/s	1	\$ 163.00	\$ 163.00
38	Sliding door lock n/s	1	\$ 392.00	\$ 392.00
39	Sliding door lock sensor n/s	1	\$ 169.00	\$ 169.00
Subtotal				\$ 18,244.20
List discount				25.00%
Total				\$ 13,683.15

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	16	\$ 4.50	\$ 72.00
2	Front door speaker n/s	1	\$ 350.00	\$ 350.00
3	Head lamp n/s clips	4	\$ 4.50	\$ 18.00
4	Front door inner trim board n/s clips	8	\$ 4.50	\$ 36.00
5	Front door pillar inner trim n/s clips	6	\$ 4.50	\$ 27.00
6	Front step panel garnish n/s bolts	4	\$ 4.50	\$ 18.00
7	Front wheel cowling n/s clips	6	\$ 4.50	\$ 27.00
8	Front wheel n/s	1	\$ 450.00	\$ 450.00
9	Front wheel outer cover n/s	1	\$ 120.00	\$ 120.00
10	Front tyre 195R15C n/s	1	\$ 280.00	\$ 280.00
10	Front door company sticker n/s	1	\$ 500.00	\$ 500.00
11	Front door LTA sticker n/s	1	\$ 25.00	\$ 25.00
12	Sliding door inner trim clips n/s	8	\$ 4.50	\$ 36.00
13	Sliding door company stickers n/s	1	\$ 1,000.00	\$ 1,000.00
14	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 3,009.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove and refit n/s front and sliding door components, check and alignment.	0.5	\$ 100.00
4	To disconnect doors wire harness of electrical component to facilitate repairs, reconnect and check power window function.	0.25	\$ 50.00

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental claim(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Repair Estimate

5	To remove and refit n/s front door glass to facilitate repair.	0.5	\$	100.00
6	To remove and refit n/s front tyre to replace rim. To perform tyre balancing and wheel alignment.	0.75	\$	nn 150.00
7	To remove and refit n/s front undercarriage for replacement of parts.	1.25	\$	nn 250.00
8	Supply spray paint material and necessary items to respray affected area / panel.	6	\$	1,200.00
9	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	3,200.00

601

X

X

6601

601

Estimate Grand Total			\$	19,892.15
----------------------	--	--	----	-----------