



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22005790/Eqy3e2	
			Date: 28/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 6325A	Veh. Inspected	SKZ 1116B
	Policy No.	D-22099187MFBP	Coverage (\$)	0.00
	Claim No.	D22001851MFBP	Excess (\$)	0.00
	Assign From	CAROLINE	Assign Date	16/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDC2539462F560427	Colour	WHITE
	Odometer	36352 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	MICHELIN	5 mm
	L/H Front Tyre	235/55 R18	MICHELIN	5 mm
	R/H Rear Tyre	235/55 R18	MICHELIN	5 mm
	L/H Rear Tyre	235/55 R18	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/06/2022	Inspection Date	21/06/2022
	Survey held at	MAXIMUS RACING PTE LTD 7 SOON LEE STREET #05-05 SINGAPORE 627608		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	