

MAXIMUS AUTO SERVICES PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 9797 3113 / Fax : +65 6250 1081

E-mail : Sales@MaximusRacing.com

ESTIMATION FOR SKZ1116B

Requested By: MS First Capital - Motor Claims Department

Address: 6 Raffles Quay, Singapore 048580

Tel:

Reference No: Q-21-138

Date: 16/6/2022

Terms: **Cash**



Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: D21MTPV01008321 // 14/6/2022 Drive In: 15/6/2022 Vehicle Make/Model: Mercedes Benz GLC250 Vehicle Number: SKZ1116B Manufacturing Year: 2018 Engine: 27492031700915 Chassis No: WDC2539462F560427				
	Rear Bumper / <i>OD</i>	1	\$ 800.00	10%	\$ 720.00 ✓
	Rear Bumper Lower / <i>CNT</i>	1	\$ 650.00	10%	\$ 585.00 ✓
	Bumper Bracket - Left ? <i>X</i> NN	1	\$ 180.00	10%	\$ 162.00
	Bumper Bracket - Right ? <i>X</i> NN	1	\$ 180.00	10%	\$ 162.00
	Bumper Bracket - Center ? <i>X</i> NN	1	\$ 180.00	10%	\$ 162.00
	Bumper Trim / <i>CNT</i>	1	\$ 400.00	10%	\$ 360.00 ✓
	Parking Sensor <i>X</i> NN	2	\$ 180.00	10%	\$ 324.00
	Rear Reinforcement Bar <i>X</i> NN	1	\$ 720.00	10%	\$ 648.00
	Rear Tow Hook Cover / <i>CNT</i>	1	60		Pending 54 ✓
					1719
	Miscellaneous - Bolts, Nuts, Screws, Clips, etc nec	1 set		30	\$ 50.00
	Remove & renew damaged parts, straighten & realign affected areas and	1		250	\$ 500.00
	Respray affected areas	1		230	\$ 500.00
	To apply cavity wax coating on affected areas (Coating)	1		150	\$ 150.00 200 ✓
	Labour To Use Mercedes Xantry To Perform Parking Sensor Calibration	1		80	\$ 100.00
					790
					total - 2509
					L/S - 2007.20
					= 2000

LKK Auto Consultants notify
the Repairer of the
• To resurvey before
• To display damage
• Parts prices
• Third parties
• No illegal
• Supplemental
is subject to the
Acknowledged by (key, date)
Signature:
Date:

ster (LKR)
21/6/22, 11:11
m PL
3 41
L/S
M H Y