

Tough

REF: CS/CT/22005791/Try.S.

ASSIGNMENT

Vehicle: IN / OUT

OTS Frt.
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

[illegible]

Category	Value
1	10
2	20
3	30
4	40
5	50
6	60
7	70
8	80
9	90
10	100
TOTAL	500

LEONARD S. GREEN / I.B.J. 17

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Tax Invoice
Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
TAN
GUAT KING
31 VERDE GROVE
SINGAPORE 688563

Document no.
Document date 04-07-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022018200/ 1
Job order date 22-06-2022
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMT2688T	5C23EZB0	31-01-2020	VWVZZZ16ZKM710170	NBS succ. BMTDESIG 77 D7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	TO ALIGN LED HEADLIGHT				#1	100.00	107.00
9801B001	WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R TYRE & BALANCING				#1	50.00	53.50
5C5821022D	Fender	1	pcs.	655.47	#1	655.47	701.35
	SCK A/O-24/6/2022						
5C0601025AKAX1	Alloy Wheel Black-Glossy	1	pcs.	1,746.54	#1	1,746.54	1,868.80
	RIM SCK A/O-25/6/2022						
311601361	Rubber Valve	1	pcs.	3.85	#1	3.85	4.12
5C5857508Q 9B9	Rear View Mirror Housing	1	pcs.	687.67	#1	687.67	735.81
3C8857538 GRU	Mirror Cap Primed	1	pcs.	203.38	#1	203.38	217.62
5C5857522A	Mirror Glass	1	pcs.	206.72	#1	206.72	221.19
5C5807184A	Guide Piece	1	pcs.	43.29	#1	43.29	46.32
	RHS BUMPER BRACKET (SIDE)						
5C5807183A	Guide Piece	1	pcs.	43.29	#1	43.29	46.32
	LHS BUMPER BRACKET (SIDE)						
5C5807773E	Holder For Cover Bumper	1	pcs.	53.98	#1	53.98	57.76
	LH						
5C5807774E	Holder For Cover Bumper	1	pcs.	53.98	#1	53.98	57.76
	RH						
3C0973737	Flat Contact Housing With	1	pcs.	21.54	#1	21.54	23.05
	H/LAMP WIRE HOUSING						
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	3	pcs.	800.00	#1	2,400.00	2,568.00
	CHINA TAIPING DIRECT						
	DOA:8/6/2022						
	TP VEH NO: XE6881Z						
	SURVEY BY:						

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,270.00	8,639.71	7%	693.68	9,909.71	10,603.39
Total	1,270.00	8,639.71		693.68	9,909.71	10,603.39

Customer

Tanym 27495749
WP: 4/7/22 E345
tanym@khant.com
05 days
Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: