

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : Sompso Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

TEL: FAX:
ATTN: Motor Claim Department

ESTIMATE

No : 22061005
Date : 10/06/2022
Policy No : D21MTPV01015985
Veh Reg No : SJA4773C
Make / Model : MAZDA 3
Your Ref No : 22/SP/OD-293(06)
Claim Type : OD CLAIM
Accident Date : 09/06/2022

Discription	Quantity	List Price	Amount
Cost Price			S\$ S\$
1 REAR BOOT	1 PC		\$580.00
2 REAR BOOT LOGO	1 PC		\$65.00
3 REAR BOOT " MAZDA " PLATE	1 PC		\$45.00
4 REAR BOOT "3 " PLATE	1 PC		\$25.00
5 REAR BOOT "SP" PLATE	1 PC		\$35.00
6 REAR BOOT INNER RUBBER	1 PC		\$165.00
7 REAR BOOT LOCK	1 PC		\$210.00
8 REAR BUMPER	1 PC		\$480.00
9 REAR BUMPER RETAINER	2 PCS	\$35.00	\$70.00
10 REAR BUMPER CLIPS	10 PCS	\$2.50	\$25.00
11 REAR BUMPER INNER SPONGE	1 PC		\$150.00
12 REAR BUMPER REINFORCEMENT	1 PC		\$280.00
13 REAR NUMBER PLATE LAMP	2 PCS	\$65.00	\$130.00
14 REAR END PANEL	1 PC		\$450.00
15 REAR END PANEL TOP TRIM	1 PC		\$155.00
16 TAIL LAMP OUTER	2 PCS	\$380.00	\$760.00
17 TAIL LAMP INNER	2 PCS	\$250.00	\$500.00
	Subtotal		\$4,125.00
	10.00%		\$412.50
			\$4,537.50
SPECIAL NET:			
1 REAR BOOT SEALANT			\$60.00
2 REAR END PANEL SEALANT			\$60.00
3 REVERSE SENSOR			\$250.00
4 REAR NUMBER PLATE			\$40.00
	TOTAL		\$410.00
Labour			
1 WIRE CHECKING			\$30.00
2 TRANSFER BOOT COMPONENT			\$100.00
3 REMOVE & REFIX REAR BOOT UPHOLSTERY			\$100.00
4 CAVITY PROTECTION ON ALL AFFECTED AREAS			\$100.00
5 REMOVE & REFIX REAR SENSOR			\$80.00
6 LABOUR CHARGE			\$800.00
7 SPRAY PAINTING			\$800.00
	TOTAL		\$2,010.00

Amount Before Excess **\$6,957.50**
Add GST @7% **\$487.03**
Total Amount Payable **\$7,444.53**

For SME MOTOR PTE LTD


AUTHORISED SIGNATURE