



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005796/Uvy3n2	
			Date: 29/06/2022	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SJA 4773C
	Policy No.	D21MTPV01015985	Coverage (\$)	0.00
	Claim No.	CMTD2202028/LOR	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	17/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 SP (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	JM6BK106270361707	Colour	RED
	Odometer	169733 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	PIRELLI	5 mm
	L/H Front Tyre	205/55 R16	PIRELLI	5 mm
	R/H Rear Tyre	205/55 R16	PIRELLI	5 mm
	L/H Rear Tyre	205/55 R16	PIRELLI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/06/2022	Inspection Date	20/06/2022
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$40,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	