



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22005797/Evy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	05/10/2022
HEMMANT ROAD SINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 527U	Veh. Inspected	SLS 5170S	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/033	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	17/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0160615	Colour	BLUE	
Odometer	356604 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	4 mm	
L/H Front Tyre	205/55 R16	DUNLOP	4 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2022	Inspection Date	21/06/2022	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 74 Kian Teck Road Singapore 628800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	