

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22005798/y3	
	300 BEACH ROAD			Date:	18/06/2022	
	#17-04/07 THE CC	DNCOURSESINGAPORE 199555		Cada	LDC2	
1.		Dollov Dortiouloro	. /TUIDD DADT\	Code:		
1.	Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. GBF 702C Veh. Inspected FBN 6148X					
		GBF 702G		<u>. </u>		
	Policy No.	00/00/00 // / / / / / / / / / / / / / /	Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/025922	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		16/06/2022	
2.						
	Make & Model		C.C		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	11/06/2022	Inspection Da	te		
	Survey held at	A-TEC AUTOMOTIVE PTE LTD)			
		8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					