


ASSIGNMENT:

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR 1868A Yr Regn: 29/6/17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: KIA Forte c.c. 1591
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading 79494 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAF J 111 M H 57137
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rm / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 21/5/22 Cycle D.O.I. 21/6/22

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MIV-64K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:


Transportation:

S + RS \$ _____

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Choo Siang Blk 256 Serangoon Central Drive #07-36 Singapore 550256 Contact No Mobile: 93822021	Cust No/Name /Lim Choo Siang Reg No/Reg Date SLQ1868A / 29/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MH5721371 Engine No G4FGGH637550 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	23/05/2022/ 12:57	BLC	442 / CocoLu	51447
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	1				3200.00
RENEW REAR BUMPER, REAR FENDER RH, REPAIR REAR LAMP HOUSING RH					2560
E PNT88000					300.00
REMOVE & INSTALL REAR WINDSCREEN					80.00
M SUNDRY					
SEALANT FOR WINDSCREEN					
E PNT98000					1650.00
SRPAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR LAMP HOUSING RH					1190
A 90000001					30.00
CHECK WIRING & ELECTRICAL SYSTEM					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
M SUNDRY					40.00
APPLY SEALANT FOR ACCIDENT PORTION					
E PNT88000					300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER TRIMS					260
M SUNDRY					20.00
Sundry					
M COVER-RR BUMPER	1.00	688.00	00.00		688.00
M GUARD-BUMPER REAR,RH	1.00	23.00	00.00		23.00
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	39.00	00.00		39.00
M PANEL ASSY-QUARTER OUTER,RH	1.00	1673.00	00.00		1673.00
M PANEL ASSY-RR COMB LAMP HSG,RH	1.00	229.00	00.00		229.00
M LAMP ASSY-REAR COMBINATION,RH	1.00	368.00	00.00		368.00
M MOULDING-REAR WINDOW GLASS	1.00	32.00	00.00		32.00

Steve (LKK)
 21/6/22, 1:00p

m n
 P/P
 H BL Y

Confirm & accepted by	LKK Auto Consultants hence notify the Repairer of the following:	8 dys
	- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed	
Authorized signatory and company stamp		
	7% GST on Nett 8,952.00 826.64 Total Payable 9,578.64	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.