



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Choo Siang  Blk 256 Serangoon Central Drive #07-36 Singapore 550256  Contact No Mobile: 93822021	Cust No/Name /Lim Choo Siang Reg No/Reg Date SLQ1868A / 29/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MH5721371 Engine No G4FGGH637550 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	23/05/2022/ 12:57	BLC	442 / CocoLu	51447			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
RENEW REAR BUMPER, REAR FENDER RH, REPAIR REAR LAMP HOUSING RH								300.00
E PNT88000								80.00
REMOVE & INSTALL REAR WINDSCREEN								
M SUNDRY								1650.00
SEALANT FOR WINDSCREEN								
E PNT98000								30.00
SRPAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR LAMP HOUSING RH								
A 90000001								280.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								40.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								300.00
APPLY SEALANT FOR ACCIDENT PORTION								
E PNT88000								20.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER TRIMS								
M SUNDRY								
Sundry					1.00	688.00	00.00	688.00
M COVER-RR BUMPER					1.00	23.00	00.00	23.00
M GUARD-BUMPER REAR,RH					1.00	39.00	00.00	39.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	1673.00	00.00	1673.00
M PANEL ASSY-QUARTER OUTER,RH					1.00	229.00	00.00	229.00
M PANEL ASSY-RR COMB LAMP HSG,RH					1.00	368.00	00.00	368.00
M LAMP ASSY-REAR COMBINATION,RH					1.00	32.00	00.00	32.00
M MOULDING-REAR WINDOW GLASS								

Confirm &amp; accepted by

7% GST on	8,952.00	8,952.00
	626.64	
Total Payable		9,578.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.